

OIL ANALYSIS REPORT

Sample Rating Trend

WEAR

Machine Id

24-KC-1 SOUTH BRIDGE GEAR

Gearbox

GEAR OIL ISO 220 (--- GAL)

DIAGNOSIS

Recommendation

Little or no information is provided as to the component and lubricant being tested. Recommendations are therefore generic in nature and may not apply to the current application. Please forward information as to equipment type, reservoir capacity, lubricant type and any pertinent information to allow for a more accurate assessment. We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. Please specify the brand, type, and viscosity of the oil on your next sample.

Lead ppm levels are abnormal. Bearing and/or bushing wear is indicated.

Contamination

There is no indication of any contamination in the


Fluid Condition

The AN level is acceptable for this fluid. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

				Jun2024		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0890722		
Sample Date		Client Info		06 Jun 2024		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
CONTAMINATION	١	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG		
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*		0		
Iron	ppm	ASTM D5185(m)	>200	13		
Chromium	ppm	ASTM D5185(m)	>15	0		
Nickel	ppm	ASTM D5185(m)	>15	<1		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		0		
Aluminum	ppm	ASTM D5185(m)	>25	<1		
Lead	ppm	ASTM D5185(m)	>100	<u>^</u> 251		
Copper	ppm	ASTM D5185(m)	>200	12		
Tin	ppm	ASTM D5185(m)	>25	1		
Antimony	ppm	ASTM D5185(m)	>5	0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
	ррпп	A31W D3103(III)		U		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	50	2		
Barium	ppm	ASTM D5185(m)	15	<1		
Molybdenum	ppm	ASTM D5185(m)	15	0		
Manganese	ppm	ASTM D5185(m)		0		
Magnesium	ppm	ASTM D5185(m)	50	<1		
Calcium	ppm	ASTM D5185(m)	50	5		
Phosphorus	ppm	ASTM D5185(m)	350	267		
Zinc	ppm	ASTM D5185(m)	100	12		
Sulfur	ppm	ASTM D5185(m)	12500	7630		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>50	2		
Sodium	ppm	ASTM D5185(m)		3		
Potassium	ppm	ASTM D5185(m)	>20	<1		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*	0.85	0.44		



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No.

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : WC0890722 Lab Number : 02644703 Unique Number : 5802242

Test Package : IND 2

To discuss this sample report, contact Customer Service at 1-800-268-2131.

Received **Tested**

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Diagnosed

: 28 Jun 2024 : 02 Jul 2024 : 02 Jul 2024 - Kevin Marson

Vale - Copper Cliff Smelter COPPER CLIFF SMELTER WAREHOUSE, 155 BALSAM ST. COPPER CLIFF, ON CA P0M 1N0

Contact: Andy Kozachanko andrew.kozachanko@vale.com T: (705)682-6687

F: (705)682-6939

Validity of results and interpretation are based on the sample and information as supplied. Report Id: INCOCCSMR [WCAMIS] 02644703 (Generated: 07/02/2024 10:25:37) Rev: 1

Contact/Location: Andy Kozachanko - INCOCCSMR