


PROBLEM SUMMARY

[FROM STRAINERS] **SULLAIR-E 8**


Component

Refrigeration Compressor

USPI 1009-68 SC (--- GAL)



COMPONENT CONDITION SUMMARY



RECOMMENDATION

PROBLEMATIC TEST RESULTS

Sample Status **ABNORMAL** Visc @ 40°C cSt ASTM D445 **2.46**

Customer Id: TYSEMPPRO Sample No.: USP217356 Lab Number: 05303449 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data: System Automation +1 905-569-8600 x230 Kevin.Marson@wearcheck.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS




OIL ANALYSIS REPORT

[FROM STRAINERS] **SULLAIR-E 8**

Refrigeration Compressor USPI 1009-68 SC (--- GAL)

DIAGNOSIS




				Jul2021		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		USP217356		
Sample Date		Client Info		14 Jul 2021		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
FLUID PROPERT	TES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445		<u>2.46</u>		
SAMPLE IMAGES	3	method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image
GRAPHS						
Ferrous Alloys						
iron						
5 - nanananan nickel						
0 12			12/			
Jull 4/2:			Jul14/21.			
Non-ferrous Metal	S					
10 copper						
5tin						
0						
Jul14/2			Jul14/21-			
→ Viscosity @ 40°C			7			
Viscosity @ 40 C						
53						
32						
1+						



OIL ANALYSIS REPORT

GRAPHS







Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 9582409

Test Package : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : USP217356 Received : 05303449 Diagnosed

: 15 Jul 2021 : 02 Oct 2023 Diagnostician : System

TYSON FOODS - EMPORIA PROCESSING

2101 WEST SIXTH EMPORIA, KS US 66801

Contact: SERVICE MANAGER

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:

F: