

# **PROBLEM SUMMARY**

Sample Rating Trend


VISCOSITY




Machine Id
7
Component
Gearbox

NOT GIVEN (--- GAL)







### RECOMMENDATION

Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS										
Sample Status				ATTENTION						
Particles >4µm		ASTM D7647	>20000	<b>23268</b>						
Oil Cleanliness		ISO 4406 (c)	>21/19/16	<u>22/19/14</u>						
Visc @ 40°C	cSt	ASTM D445		<b>15.9</b>						

Customer Id: COUBOW Sample No.: USP232796 Lab Number: 05633623 Test Package: IND 2 To manage this report scan the QR code

To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 dougb@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com


## RECOMMENDED ACTIONS

There are no recommended actions for this sample.

## HISTORICAL DIAGNOSIS



# **OIL ANALYSIS REPORT**







Machine Id Component Gearbox

**NOT GIVEN (--- GAL)** 

## DIAGNOSIS

#### Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

#### Contamination

There is a moderate amount of silt (particulates < 6 microns in size) present in the oil.


## Fluid Condition

The oil viscosity is lower than normal. Confirmed. The AN level is acceptable for this fluid.

				Aug2022		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		USP232796		
Sample Date		Client Info		24 Aug 2022		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ATTENTION		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	31		
Chromium	ppm	ASTM D5185m	>15	0		
Nickel	ppm	ASTM D5185m	>15	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	<1		
Lead	ppm	ASTM D5185m	>100	<1		
Copper	ppm	ASTM D5185m	>200	<1		
Tin	ppm	ASTM D5185m	>25	0		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		2		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m		0		
Calcium	ppm	ASTM D5185m		2		
Phosphorus	ppm	ASTM D5185m		565		
Zinc	ppm	ASTM D5185m		52		
Sulfur	ppm	ASTM D5185m		575		
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	10		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	1		
Water	%	ASTM D6304	>0.2	0.003		
ppm Water	ppm	ASTM D6304	>2000	29.3		
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4μm		ASTM D7647	>20000	<b>23268</b>		
Particles >6µm		ASTM D7647	>5000	3135		
Particles >14µm		ASTM D7647	>640	156		
Particles >21µm		ASTM D7647	>160	29		
Particles >38μm		ASTM D7647	>40	0		
Particles >71μm		ASTM D7647	>10	0		
Oil Cleanliness		ISO 4406 (c)	>21/19/16	<b>22/19/14</b>		
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.61		



## **OIL ANALYSIS REPORT**





Certificate L2367

Sample No. Lab Number **Unique Number** 

: USP232796 : 05633623 : 10118144 Test Package : IND 2

Received Diagnosed

: 09 Sep 2022 Diagnostician : Doug Bogart

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

2840 PIONEER DR **BOWLING GREEN, KY** US 42101

Contact: TERRY COLLINS

Contact/Location: TERRY COLLINS - COUBOW

terry.collins@kroger.com T:

F: (270)793-5647