

PROBLEM SUMMARY

Sample Rating Trend ISO


3057932 (S/N 1267)

Component

Compressor

KAESER SIGMA (OEM) M-460 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS									
Sample Status			ABNORMAL	ATTENTION					
Particles >6µm	ASTM D7647	>1300	41279	<u>▲</u> 1513					
Particles >14µm	ASTM D7647	>80	3071	<u> </u>					
Particles >21µm	ASTM D7647	>20	690	△ 32					
Particles >38µm	ASTM D7647	>4	<u> </u>	2					
Oil Cleanliness	ISO 4406 (c)	>/17/13	<u>4</u> 24/23/19	<u></u> 18/14					

Customer Id: NEWFRA Sample No.: KCP49349 Lab Number: 05640356 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 dougb@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Fluid			?	Oil and filter change at the time of sampling has been noted.			
Change Filter			?	Oil and filter change at the time of sampling has been noted.			

HISTORICAL DIAGNOSIS

04 Feb 2021 Diag: Don Baldridge





Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is a moderate amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend



ISO



3057932 (S/N 1267)

Component

Compressor

KAESER SIGMA (OEM) M-460 (--- GAL)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is a high amount of particulates present in the oil.


Fluid Condition

The condition of the oil is suitable for further service.

			Feb 2021	Sep2022		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		KCP49349	KCP27855	
Sample Date		Client Info		07 Sep 2022	04 Feb 2021	
Machine Age	hrs	Client Info		29721	26090	
Oil Age	hrs	Client Info		3631	3131	
Oil Changed		Client Info		Changed	Changed	
Sample Status				ABNORMAL	ATTENTION	
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	<1	<1	
Chromium	ppm	ASTM D5185m	>10	0	0	
Nickel	ppm	ASTM D5185m	>3	0	0	
Titanium	ppm	ASTM D5185m	>3	0	0	
Silver	ppm	ASTM D5185m	>2	<1	0	
Aluminum	ppm	ASTM D5185m	>10	<1	<1	
Lead	ppm	ASTM D5185m	>10	<1	0	
Copper	ppm	ASTM D5185m	>50	12	10	
Tin	ppm	ASTM D5185m	>10	<1	<1	
Antimony	ppm	ASTM D5185m			0	
Vanadium	ppm	ASTM D5185m		0	0	
Cadmium	ppm	ASTM D5185m		<1	0	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	0	12	
Barium	ppm	ASTM D5185m	90	0	0	
Molybdenum	ppm	ASTM D5185m	0	0	0	
Manganese	ppm	ASTM D5185m		<1	0	
Magnesium	ppm	ASTM D5185m	100	25	31	
Calcium	ppm	ASTM D5185m	0	<1	0	
Phosphorus	ppm	ASTM D5185m	0	1	2	
Zinc	ppm	ASTM D5185m	0	47	60	
Sulfur	ppm	ASTM D5185m	23500	17942	17823	
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	7	10	
Sodium	ppm	ASTM D5185m		10	5	
Potassium	ppm	ASTM D5185m	>20	2	0	
Water	%	ASTM D6304	>0.05	0.021	0.015	
ppm Water	ppm	ASTM D6304	>500	216.7	155.9	
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647		120625	4169	
Particles >6µm		ASTM D7647	>1300	<u>41279</u>	<u>▲</u> 1513	
Particles >14μm		ASTM D7647	>80	<u> </u>	<u> </u>	
Particles >21µm		ASTM D7647	>20	690	▲ 32	
Particles >38μm		ASTM D7647	>4	<u> </u>	2	
Particles >71μm		ASTM D7647	>3	0	0	
Oil Cleanliness		ISO 4406 (c)	>/17/13	<u>24/23/19</u>	<u> </u>	
FLUID DEGRADA	TION	method	limit/base	current	history1	history2



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: KCP49349 : 05640356

: 10129886

Received : 13 Sep 2022 Diagnosed

: 15 Sep 2022

Diagnostician : Doug Bogart Test Package : IND 2 (Additional Tests: KF, PrtCount)

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

NEW VIEW MARBLE AND GRANITE

1 MASTER DR FRANKLIN, MA US 02038

Contact: Service Manager newviewgranite1@gmail.com

T:

F: