

PROBLEM SUMMARY

Sample Rating Trend

ISO




BIOFLO AWS 46 SF

Component New (Unused) Oil

{not provided} (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

This is the baseline readout on this new (unused) oil.

PROBLEMATIC TEST RESULTS									
Sample Status			ATTENTION						
Particles >4µm	ASTM D7647	>5000	△ 6833						
Particles >6μm	ASTM D7647	>1300	<u> </u>						
Oil Cleanliness	ISO 4406 (c)	>19/17/14	20/18/14						

Customer Id: BIOELK Sample No.: BB0000140 Lab Number: 05810711 Test Package: PLANT

To manage this report scan the QR code

To discuss the diagnosis or test data: Angela Borella +1 800-237-1369 angela.borella@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

Sample Rating Trend




BIOFLO AWS 46 SF

Component

New (Unused) Oil

{not provided} (--- GAL)



DIAGNOSIS


Recommendation

This is the baseline readout on this new (unused)

				Apr2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		BB0000140		
Sample Date		Client Info		03 Apr 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ATTENTION		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>5	0		
Chromium	ppm	ASTM D5185m	>5	0		
Nickel	ppm	ASTM D5185m	>5	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m	>5	0		
Aluminum	ppm	ASTM D5185m	>5	0		
Lead	ppm	ASTM D5185m	>5	0		
Copper	ppm	ASTM D5185m	>5	0		
Tin	ppm	ASTM D5185m	>5	0		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		0		
Magnesium	ppm	ASTM D5185m		0		
Calcium	ppm	ASTM D5185m		0		
Phosphorus	ppm	ASTM D5185m		125		
Zinc	ppm	ASTM D5185m		0		
Sulfur	ppm	ASTM D5185m		1323		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	4		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	1		
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4μm		ASTM D7647	>5000	△ 6833		
Particles >6µm		ASTM D7647	>1300	<u>^</u> 2118		
Particles >14µm		ASTM D7647	>160	157		
Particles >21µm		ASTM D7647	>40	19		
Particles >38µm		ASTM D7647	>10	1		
Particles >71µm		ASTM D7647	>3	0		
Oil Cleanliness		ISO 4406 (c)	>19/17/14	<u>^</u> 20/18/14		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.49		



OIL ANALYSIS REPORT





Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: BB0000140 : 05810711 : 10413503

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 04 Apr 2023 Diagnosed

: 11 Apr 2023 Diagnostician : Angela Borella Test Package : PLANT (Additional Tests: FT-IR, KV100, VI)

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

BioBlend - Elk Grove VIllage

1500 JARVIS AVE ELK GROVE VILLAGE, IL US 60007

Contact: DAN GABRIEL dan.gabriel@bioblend.com

T:

F: