



PROBLEM SUMMARY



Machine Id **14AR10 (S/N 06EX850350)** Component

Refrigeration Compressor Fluid SOLEST LT-32 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS											
Sample Status				MARGINAL	NORMAL	MARGINAL					
Water	%	ASTM D6304	>0.01	<u> </u>	0.008	▲ 0.024					
ppm Water	ppm	ASTM D6304	>100	🔺 165.5	85.6	<u> </u>					

Customer Id: TALCLA Sample No.: WC0792602 Lab Number: 05830732 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 <u>customerservice@wearcheck.com</u>

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

23 Jan 2023 Diag: Don Baldridge



Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the component. The amount and size of particulates present in the system is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.




view report

31 Oct 2022 Diag: Angela Borella



No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is a trace of moisture present in the oil. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.








No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is a trace of moisture present in the oil. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.







OIL ANALYSIS REPORT

Sample Rating Trend

WATER

Machine Id **14AR10 (S/N 06EX850350)** Component

Refrigeration Compressor Fluid SOLEST LT-32 (--- GAL)

DIAGNOSIS

A Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is a trace of moisture present in the oil. The amount and size of particulates present in the system are acceptable.

Fluid Condition


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.


2013 Jan2015 An2016 Jan2017 Seg2016 Dec2019 Fe2021 May/022


SAMPLE INFORM	/IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0792602	WC0744464	WC0744462
Sample Date		Client Info		21 Apr 2023	23 Jan 2023	31 Oct 2022
Machine Age	mths	Client Info		0	0	0
Oil Age	mths	Client Info		0	0	0
Oil Changed		Client Info		N/A	Not Changd	N/A
Sample Status				MARGINAL	NORMAL	MARGINAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	0	<1	0
Chromium	ppm	ASTM D5185m	>10	0	0	0
Nickel	ppm	ASTM D5185m		0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>10	0	2	2
Lead	ppm	ASTM D5185m	>10	0	_ <1	0
Copper	ppm	ASTM D5185m		0	0	0
Tin	ppm	ASTM D5185m	>10	0	<1	<1
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		<1	0	0
Magnesium	ppm	ASTM D5185m		2	0	0
Calcium	ppm	ASTM D5185m		0	0	0
Phosphorus	ppm	ASTM D5185m		6	6	10
Zinc	ppm	ASTM D5185m		0	0	0
Sulfur	ppm	ASTM D5185m		584	10	1
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	0	<1	<1
Sodium	ppm	ASTM D5185m		0	0	0
Potassium	ppm	ASTM D5185m	>20	<1	0	0
Water	%	ASTM D6304	>0.01	A 0.016	0.008	▲ 0.024
ppm Water	ppm	ASTM D6304	>100	165.5	85.6	▲ 240.2
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>10000	714	1769	1546
Particles >6µm		ASTM D7647	>2500	124	293	188
Deutleles d'Aure		ASTM D7647	>320	13	8	5
Particles >14µm						
Particles >14µm Particles >21µm		ASTM D7647	>80	4	2	1
		ASTM D7647 ASTM D7647	>80 >20	4 0	2 0	1 0
Particles >21µm			>20			
Particles >21µm Particles >38µm		ASTM D7647	>20	0	0	0
Particles >21µm Particles >38µm Particles >71µm	TION	ASTM D7647 ASTM D7647	>20 >4	0 0	0 0	0 0





OIL ANALYSIS REPORT















Bottom

GRAPHS



To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: (919)359-4362

F: (919)359-4767

kenneth.terry@grifols.com

Certificate L2367

Laboratory

Sample No.

Lab Number