

## **PROBLEM SUMMARY**

Sample Rating Trend

**VIS DEBRIS** 

# KAESER BSD50T 5248346 (S/N 1146)

Compressor

KAESER SIGMA (OEM) S-460 (--- GAL)

**COMPONENT CONDITION SUMMARY** 

No relevant graphs to display

## RECOMMENDATION

No corrective action is recommended at this time. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample.

PROBLEMATIC TEST RESULTS						
Sample Status				ABNORMAL	ABNORMAL	ATTENTION
Debris	scalar	*Visual	NONE	▲ MODER	NONE	NONE

Customer Id: SHEMACKC Sample No.: KC107793 Lab Number: 05849766 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

### **RECOMMENDED ACTIONS**

Action	Status	Date	Done By	Description
Change Fluid			?	Oil and filter change at the time of sampling has been noted.
Change Filter			?	Oil and filter change at the time of sampling has been noted.
Alert			?	We were unable to perform a particle count due to a high concentration of particles present in this sample.

## HISTORICAL DIAGNOSIS

### 16 Nov 2022 Diag: Don Baldridge

ISO



No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



## 06 Oct 2021 Diag: Don Baldridge

ISO



The filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is a moderate amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

# View report

## 12 Mar 2021 Diag: Jonathan Hester

ISO



Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





## **OIL ANALYSIS REPORT**

SAMPI

Sample Rating Trend



history2

Machine Id

## KAESER BSD50T 5248346 (S/N 1146)

Component

Compressor

KAESER SIGMA (OEM) S-460 (--- GAL)

## **DIAGNOSIS**

### Recommendation

No corrective action is recommended at this time. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample.

### Wear

All component wear rates are normal.

## Contamination

Moderate concentration of visible dirt/debris present in the oil.

## **Fluid Condition**

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Number	Client Info	K	C107793	KC103134
LE INFORMATION	method	limit/base	current	history1
l 1146)	φ/2015 Seg/2015	Jan-2016 Des2016 Aug2017	Ju2018 Sm2019 Mar2021	Nov2022

Sample Number		Client Info		KC107793	KC103134	KC98923
Sample Date		Client Info		08 May 2023	16 Nov 2022	06 Oct 2021
Machine Age	hrs	Client Info		36611	34838	29669
Oil Age	hrs	Client Info		4485	2685	2067
Oil Changed		Client Info		Changed	Not Changd	Not Changd
Sample Status				ABNORMAL	ABNORMAL	ATTENTION
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	<1	<1	<1
Chromium	ppm	ASTM D5185m	>10	0	0	0
Nickel	ppm	ASTM D5185m	>3	0	0	0
Titanium	ppm	ASTM D5185m	>3	0	0	0
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>10	<1	<1	4
Lead	ppm	ASTM D5185m	>10	0	0	0
Copper	ppm	ASTM D5185m	>50	6	7	11
Tin	ppm	ASTM D5185m	>10	0	0	<1
Antimony	ppm	ASTM D5185m				<1
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	<1
Barium	ppm	ASTM D5185m	90	8	<1	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		<1	<1	0
Magnesium	ppm	ASTM D5185m	90	37	37	7
Calcium	ppm	ASTM D5185m	2	<1	0	0
Phosphorus	ppm	ASTM D5185m		<1	0	2
Zinc	ppm	ASTM D5185m		0	6	0
CONTAMINANTS	}	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	0	0	0
Sodium	ppm	ASTM D5185m		15	12	2
Potassium	ppm	ASTM D5185m	>20	3	0	<1
Water	%	ASTM D6304	>0.05	0.014	0.011	0.012
ppm Water	ppm	ASTM D6304	>500	149.9	112.3	120.0
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647			19849	2672
Particles >6µm		ASTM D7647	>1300		<u></u> 5516	779
Particles >14µm		ASTM D7647	>80		<b>430</b>	<u> </u>
Particles >21µm		ASTM D7647	>20		<b>△</b> 98	<b>△</b> 32
Particles >38µm		ASTM D7647	>4		<u>^</u> 7	1
Particles >71µm		ASTM D7647	>3		1	0
Oil Cleanliness		ISO 4406 (c)	>/17/13		<u>\$\text{\Delta}\$ 21/20/16</u>	<b>△</b> 17/14
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.4	0.38	0.36	0.401



## **OIL ANALYSIS REPORT**







Certificate L2367

Laboratory

Sample No. Lab Number **Unique Number** 

: KC107793 : 05849766 : 10479121 Test Package : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 17 May 2023

Diagnosed : 19 May 2023 : Don Baldridge Diagnostician

**SHERWIN WILLIAMS** 7411 INDUSTRIAL PKWY MACUNGIE, PA US 18106

Contact:

T: F:

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)