

PROBLEM SUMMARY

PROBLEM SUMMAN


ALBERTSONS BREA

C-04 - ALBERTSONS BREA (S/N F0129WFMNLHGA03)


Component


Refrigeration Compressor

INDUSTRIAL IRP 717 (75 GAL)



COMPONENT CONDITION SUMMARY





RECOMMENDATION

We recommend you service the filters on this component. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS								
Sample Status				ABNORMAL				
Iron	ppm	ASTM D5185m	>8	<u></u> ▲ 66				
Particles >4µm		ASTM D7647	>10000	199459				
Particles >6µm		ASTM D7647	>2500	75305				
Particles >14µm		ASTM D7647	>320	△ 360				
Oil Cleanliness		ISO 4406 (c)	>20/18/15	<u>^</u> 25/23/16				

Customer Id: RACGAR Sample No.: USP250812 Lab Number: 05878869 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 dougb@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Filter			?	We recommend you service the filters on this component.			

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

ALBERTSONS BREA

C-04 - ALBERTSONS BREA (S/N F0129WFMNLHGA03)

Refrigeration Compressor

INDUSTRIAL IRP 717 (75 GAL)





DIAGNOSIS

Recommendation

We recommend you service the filters on this component. Resample at the next service interval to monitor.

Wear

The iron level is abnormal.

Contamination

There is a high amount of particulates present in the oil.


Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

				Jun 2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		USP250812		
Sample Date		Client Info		01 Jun 2023		
Machine Age	hrs	Client Info		98327		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>8	66		
Chromium	ppm	ASTM D5185m	>2	0		
Nickel	ppm	ASTM D5185m		0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m	>2	0		
Aluminum	ppm	ASTM D5185m	>3	0		
Lead	ppm	ASTM D5185m	>2	0		
Copper	ppm	ASTM D5185m	>8	0		
Tin	ppm	ASTM D5185m	>4	0		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m		0		
Calcium	ppm	ASTM D5185m		0		
Phosphorus	ppm	ASTM D5185m		1		
Zinc	ppm	ASTM D5185m		0		
Sulfur	ppm	ASTM D5185m		23		
CONTAMINANTS	6	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	0		
Sodium	ppm	ASTM D5185m		2		
Potassium	ppm	ASTM D5185m	>20	0		
Water	%	ASTM D6304	>0.01	0.006		
ppm Water	ppm	ASTM D6304	>100	65.2		
FLUID CLEANLIN	NESS	method	limit/base	current	history1	history2
Particles >4μm		ASTM D7647	>10000	199459		
Particles >6µm		ASTM D7647	>2500	75305		
Particles >14μm		ASTM D7647	>320	△ 360		
Particles >21µm		ASTM D7647	>80	36		
Particles >38μm		ASTM D7647	>20	1		
Particles >71μm		ASTM D7647	>4	0		
Oil Cleanliness		ISO 4406 (c)	>20/18/15	<u>^</u> 25/23/16		
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974		0.031		



OIL ANALYSIS REPORT





Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: USP250812

: 05878869 : 10523972 Test Package : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 20 Jun 2023 Received Diagnosed : 21 Jun 2023 Diagnostician : Doug Bogart

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

RACE ENGINEERING CORP

12871 WESTERN AVE, SUITE E GARDEN GROVE, CA

Contact/Location: TODD CARTER - RACGAR

US 92841

Contact: TODD CARTER tcrace@verizon.net

> T: (714)895-3488 F: (714)895-5125