

No relevant graphs to display

RECOMMENDATION

We recommend you service the filters on this component. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample.

PROBLEMATIC TEST RESULTS								
Sample Status				ABNORMAL	ABNORMAL			
Silt	scalar	*Visual	NONE	🔺 MODER	NONE			

Customer Id: CAREMP Sample No.: USP250462 Lab Number: 05901299 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 <u>dougb@wearcheckusa.com</u>

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS					
Action	Status	Date	Done By	Description	
Change Filter			?	We recommend you service the filters on this component.	
Alert			?	We were unable to perform a particle count due to a high concentration of particles present in this sample.	

HISTORICAL DIAGNOSIS



28 Sep 2022 Diag: Doug Bogart

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of particulates present in the oil. Confirm oil type. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend

SEDIMENT

EXTRUDER (S/N FF2271U01311)

Bearing Fluid USPI GEAR 460 (--- GAL)

DIAGNOSIS

Recommendation

We recommend you service the filters on this component. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample.

Wear

All component wear rates are normal.

Contamination

There is a moderate amount of visible silt present in the sample.


Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

			SepzUZZ	Jui2023		
SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		USP250462	USP219414	
Sample Date		Client Info		17 Jul 2023	28 Sep 2022	
Machine Age	hrs	Client Info		0	0	
Oil Age	hrs	Client Info		0	0	
Oil Changed		Client Info		N/A	N/A	
Sample Status				ABNORMAL	ABNORMAL	
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	7	3	
Chromium	ppm	ASTM D5185m	>20	0	0	
Nickel	ppm	ASTM D5185m	>20	0	0	
Titanium		ASTM D5185m	>20	<1	0	
Silver	ppm					
	ppm	ASTM D5185m	00	0	0	
Aluminum	ppm	ASTM D5185m	>20	<1	0	
Lead	ppm	ASTM D5185m	>20	0	0	
Copper	ppm	ASTM D5185m		<1	<1	
Tin	ppm	ASTM D5185m	>20	0	0	
Vanadium	ppm	ASTM D5185m		<1	<1	
Cadmium	ppm	ASTM D5185m		0	0	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		4	0	
Barium	ppm	ASTM D5185m		0	0	
Molybdenum	ppm	ASTM D5185m		0	<1	
Manganese	ppm	ASTM D5185m		<1	<1	
Magnesium	ppm	ASTM D5185m		1	0	
Calcium	ppm	ASTM D5185m		0	0	
Phosphorus	ppm	ASTM D5185m		74	128	
Zinc	ppm	ASTM D5185m		0	76	
Sulfur	ppm	ASTM D5185m		8584	7476	
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	2	2	
Sodium	ppm	ASTM D5185m		<1	0	
Potassium	ppm	ASTM D5185m	>20	<1	0	
Water	%	ASTM D6304	>2	0.001	0.008	
ppm Water	ppm	ASTM D6304		1.6	86.2	
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>10000		2 0338	
Particles >6µm		ASTM D7647	>2500		A 3798	
Particles >14µm		ASTM D7647	>160		4 36	
Particles >21µm		ASTM D7647	>40		1 27	
Particles >38µm		ASTM D7647	>10		2	
Particles >71µm		ASTM D7647			0	
Oil Cleanliness		ISO 4406 (c)	>20/18/14		A 22/19/16	
FLUID DEGRADA		method	limit/base	current	history1	history2
		ASTM D8045		0.38	0.57	
Acid Number (AN)	mg KOH/g	AG HVI DOU40		0.50	0.57	



OIL ANALYSIS REPORT



Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: SHAWN ANDERS - CAREMP

T:

F:

EMPORIA, KS US 66801

history2

history

history2

no image

no image