


# **PROBLEM SUMMARY**

CH 1 CIR 1 (S/N 11531D53598241)

**Refrigeration Compressor** 

**EMKARATE RL 32-3MAF (--- GAL)** 

**COMPONENT CONDITION SUMMARY** 



No relevant graphs to display

#### RECOMMENDATION

We suspect abnormal contamination may be due to sampling method. We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.

PROBLEMATIC 1	EST RE	SULTS				
Sample Status				MARGINAL	 	
Debris	scalar	*Visual	NONE	▲ MODER	 	

Customer Id: RANBARIL Sample No.: WC0751608 Lab Number: 05922246 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 dougb@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Filter			?	We recommend you service the filters on this component if applicable.		

# HISTORICAL DIAGNOSIS



# **OIL ANALYSIS REPORT**

FLUID DEGRADATION

Acid Number (AN)

method

mg KOH/g ASTM D974 0.05

limit/base

current

0.014

Sample Rating Trend

VIS DEBRIS



# CH 1 CIR 1 (S/N 11531D53598241)

Component

**Refrigeration Compressor** 

EMKARATE RL 32-3MAF (--- GAL)

### DIAGNOSIS

#### Recommendation

We suspect abnormal contamination may be due to sampling method. We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.

#### Wear

All component wear rates are normal.

#### Contamination

There is a trace of moisture present in the oil. Moderate concentration of visible dirt/debris present in the oil.

#### **Fluid Condition**

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.


				Aug2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0751608		
Sample Date		Client Info		03 Aug 2023		
Machine Age	hrs	Client Info		28758		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		Not Changd		
Sample Status				MARGINAL		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>8	0		
Chromium	ppm	ASTM D5185m	>2	0		
Nickel	ppm	ASTM D5185m		0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m	>2	0		
Aluminum	ppm	ASTM D5185m	>3	1		
Lead	ppm	ASTM D5185m	>2	0		
Copper	ppm	ASTM D5185m	>8	<1		
Tin	ppm	ASTM D5185m	>4	<1		
Vanadium	ppm	ASTM D5185m		<1		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m		0		
Calcium	ppm	ASTM D5185m		0		
Phosphorus	ppm	ASTM D5185m		275		
Zinc	ppm	ASTM D5185m		0		
Sulfur	ppm	ASTM D5185m		0		
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	<1		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	0		
Water	%	ASTM D6304	>0.01	0.201		
ppm Water	ppm	ASTM D6304	>100	2011.4		

history1

history2



## **OIL ANALYSIS REPORT**







Certificate L2367

Laboratory Sample No. Lab Number Unique Number

: WC0751608

: 05922246 : 10602193 Test Package : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 11 Aug 2023

Diagnosed : 14 Aug 2023 : Doug Bogart Diagnostician

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

**RANA MEAL SOLUTIONS** 

550 SPITZER RD BARTLETT, IL

US 60103

Contact: Service Manager