



### **PROBLEM SUMMARY**



## HCTS (S/N CB105-BL)

Servo Valve Upstream Hydraulic System Fluid DEXRON-VI (--- GAL)

### COMPONENT CONDITION SUMMARY



### RECOMMENDATION

We recommend you service the filters on this component. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS							
Sample Status		ABNORMA	ABNORMAL	ABNORMAL			
Particles >4µm	ASTM D7647 >5	000 <b>A 80434</b>	▲ 77997				
Particles >6µm	ASTM D7647 >13	300 🔺 <b>18940</b>	17386				
Particles >14µm	ASTM D7647 >1	60 🔺 <b>827</b>	<b>5</b> 46				
Particles >21µm	ASTM D7647 >4	0 🔺 142	<u> </u>				
Oil Cleanliness	ISO 4406 (c) >19	9/17/14 🔺 24/21/17	▲ 23/21/16				

Customer Id: DUNAUS Sample No.: WC0806736 Lab Number: 05927195 Test Package: PLANT



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS					
Action	Status	Date	Done By	Description	
Change Filter			?	We recommend you service the filters on this component.	

### HISTORICAL DIAGNOSIS



28 Jun 2023 Diag: Don Baldridge

We recommend you service the filters on this component. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

# view report

view report

### VISUAL METAL



We recommend you service the filters on this component. We advise that you inspect for the source(s) of metal. Resample at the next service interval to monitor. We were unable to perform a particle count due to metal particles present in this sample.Moderate concentration of visible metal present. All component wear rates are normal. No other contaminants were detected in the oil. The AN level is acceptable for this fluid.

ISO

### 25 May 2023 Diag: Don Baldridge

06 Jun 2023 Diag: Don Baldridge

We recommend you service the filters on this component. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





### **OIL ANALYSIS REPORT**

Sample Rating Trend

ISO

### HCTS (S/N CB105-BL)

Servo Valve Upstream Hydraulic System Fluid DEXRON-VI (--- GAL)

### DIAGNOSIS

### Recommendation

We recommend you service the filters on this component. Resample at the next service interval to monitor.

### Wear

All component wear rates are normal.

### Contamination

There is a high amount of particulates present in the oil.


#### **Fluid Condition**


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0806736	WC0806733	WC0806732
Sample Date		Client Info		14 Aug 2023	28 Jun 2023	06 Jun 2023
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	4	4	3
Chromium	ppm	ASTM D5185m	>20	0	0	0
Nickel	ppm	ASTM D5185m	>20	0	<1	0
Titanium	ppm	ASTM D5185m		<1	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>20	4	3	4
Lead	ppm	ASTM D5185m	>20	1	<1	<1
Copper	ppm	ASTM D5185m	>20	2	2	1
Tin	ppm	ASTM D5185m	>20	0	0	0
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	75	8	11	13
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	0	0	0	0
Manganese	ppm	ASTM D5185m		<1	0	0
Magnesium	ppm	ASTM D5185m	0	3	0	0
Calcium	ppm	ASTM D5185m	200	80	71	77
Phosphorus	ppm	ASTM D5185m	300	191	173	196
Zinc	ppm	ASTM D5185m	25	14	7	5
Sulfur	ppm	ASTM D5185m	1200	1845	1573	2010
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	1	1	<1
Sodium	ppm	ASTM D5185m		2	0	2
Potassium	ppm	ASTM D5185m	>20	4	2	2
FLUID CLEANLIN	ESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	<b>A</b> 80434	<b>A</b> 77997	
Particles >6µm		ASTM D7647	>1300	<u> </u>	17386	
Particles >14µm		ASTM D7647	>160	<u> </u>	<b>5</b> 46	
Particles >21µm		ASTM D7647	>40	<u> </u>	<mark>▲</mark> 71	
Particles >38µm		ASTM D7647	>10	1	1	
Particles >71µm		ASTM D7647	>3	0	0	
Oil Cleanliness		ISO 4406 (c)	>19/17/14	<b>A</b> 24/21/17	▲ 23/21/16	
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.72	0.77	0.71



### **OIL ANALYSIS REPORT**






VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	🔺 MODER
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.05	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	29.5	30.0	30.1	29.8
SAMPLE IMAGES		method	limit/base	current	history1	history2





Bottom



di.

Contact/Location: KEVIN SINKAR - DUNAUS