

# **PROBLEM SUMMARY**

Sample Rating Trend


**WATER** 

KAESER 8043399 (S/N 1068)

Compressor

KAESER SIGMA (OEM) S-460 (--- GAL)

## **COMPONENT CONDITION SUMMARY**



### RECOMMENDATION

Oil and filter change at the time of sampling has been noted. There is too much water present in this sample to perform a particle count. We recommend an early resample in 500 hours to monitor this condition.

PROBLEMATIC T	EST RE	SULTS				
Sample Status				ABNORMAL	ATTENTION	
Water	%	ASTM D6304	>0.05	<b>△</b> 0.172	0.012	
ppm Water	maa	ASTM D6304	>500	<b>1720</b>	129.1	

Customer Id: THEROW Sample No.: KCP48020 Lab Number: 05927271 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 ihester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDE	D ACTIONS			
Action	Status	Date	Done By	Description
Change Fluid			?	Oil and filter change at the time of sampling has been noted.
Change Filter			?	Oil and filter change at the time of sampling has been noted.

# HISTORICAL DIAGNOSIS

## 30 Sep 2022 Diag: Doug Bogart

ISC




No corrective action is recommended at this time. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is a moderate amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





# **OIL ANALYSIS REPORT**



**WATER** 

# KAESER 8043399 (S/N 1068)

Compressor

KAESER SIGMA (OEM) S-460 (--- GAL)

## **DIAGNOSIS**

#### Recommendation

Oil and filter change at the time of sampling has been noted. There is too much water present in this sample to perform a particle count. We recommend an early resample in 500 hours to monitor this condition.

### Wear

All component wear rates are normal.

#### Contamination

There is a light concentration of water present in the


### **Fluid Condition**

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

			Sep 2022	Aug2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		KCP48020	KCP50089	
Sample Date		Client Info		08 Aug 2023	30 Sep 2022	
Machine Age	hrs	Client Info		7197	2625	
Oil Age	hrs	Client Info		0	2625	
Oil Changed		Client Info		Changed	Changed	
Sample Status				ABNORMAL	ATTENTION	
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	0	<1	
Chromium	ppm	ASTM D5185m	>10	0	0	
Nickel	ppm	ASTM D5185m	>3	0	0	
Titanium	ppm	ASTM D5185m	>3	<1	0	
Silver	ppm	ASTM D5185m	>2	0	0	
Aluminum	ppm	ASTM D5185m	>10	<1	<1	
Lead	ppm	ASTM D5185m	>10	<1	0	
Copper	ppm	ASTM D5185m		17	9	
Tin	ppm	ASTM D5185m	>10	0	<1	
Vanadium	ppm	ASTM D5185m		<1	<1	
Cadmium	ppm	ASTM D5185m		0	0	
	рріп		11 11 11			
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	
Barium	ppm	ASTM D5185m	90	0	0	
Molybdenum	ppm	ASTM D5185m		0	0	
Manganese	ppm	ASTM D5185m		<1	1	
Magnesium	ppm	ASTM D5185m	90	9	30	
Calcium	ppm	ASTM D5185m	2	0	0	
Phosphorus	ppm	ASTM D5185m		6	11	
Zinc	ppm	ASTM D5185m		9	2	
Sulfur	ppm	ASTM D5185m		20109	20010	
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	<1	<1	
Sodium	ppm	ASTM D5185m		4	15	
Potassium	ppm	ASTM D5185m	>20	2	0	
Water	%	ASTM D6304	>0.05	<b>△</b> 0.172	0.012	
ppm Water	ppm	ASTM D6304	>500	<b>△</b> 1720	129.1	
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4μm		ASTM D7647			3499	
Particles >6µm		ASTM D7647	>1300		1056	
Particles >14μm		ASTM D7647	>80		<u></u> 102	
Particles >21µm		ASTM D7647	>20		20	
Particles >38μm		ASTM D7647	>4		2	
Particles >71µm		ASTM D7647	>3		0	
Oil Cleanliness		ISO 4406 (c)	>/17/13		<b>△</b> 19/17/14	
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.4	0.27	0.27	



# **OIL ANALYSIS REPORT**







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** 

: 05927271 : 10607218

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 17 Aug 2023 : KCP48020 Diagnosed : 21 Aug 2023

Diagnostician : Jonathan Hester Test Package : IND 2 ( Additional Tests: KF, PrtCount )

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) THE STORE DECOR CO

5050 BOYD BLVD ROWLETT, TX US 75088

Contact: Service Manager

T: F: