

PROBLEM SUMMARY

Sample Rating Trend

VISCOSITY




PHILIDELPHIA B-CFT

Component **Gearbox**

ROYAL PURPLE SYNFILM 68 (15 GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS										
Sample Status				ATTENTION	ABNORMAL	NORMAL				
Visc @ 40°C	cSt	ASTM D445	68	134	<u>▲</u> 111.8	141.7				

Customer Id: OXYDEE Sample No.: RP0027474 Lab Number: 05928386 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

26 Mar 2018 Diag: Jonathan Hester

WATER



We advise that you check for the source of water entry. We advise that you follow the water drain-off procedure for this component. We recommend an early resample to monitor this condition. All component wear rates are normal. Free water present. There is a light concentration of water present in the oil. The oil viscosity is lower than normal. Confirm oil type. The AN level is acceptable for this fluid.



30 May 2017 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. The water content is negligible. There is no indication of any contamination in the component. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



17 May 2017 Diag: Don Baldridge

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the component. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

VISCOSITY

PHILIDELPHIA B-CFT

Component

Gearbox

ROYAL PURPLE SYNFILM 68 (15 GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil.

▲ Fluid Condition


The oil viscosity is higher than normal. Confirm oil type. The AN level is acceptable for this fluid.


		TT O	i i							
			i							Ϊ
н			Ť							
Ш		П								۱
H			i							
			İ		+++		+++			
b2004	Nov2004	Jul2008	Jul2010	Sep 2	013 D	ec2014	0ct2015	Jul2016	May2017	Áu

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		RP0027474	RP191609	RP185153
Sample Date		Client Info		09 Aug 2023	26 Mar 2018	30 May 2017
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		Not Changd	N/A	N/A
Sample Status				ATTENTION	ABNORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	55	4	4
Chromium	ppm	ASTM D5185m	>15	0	0	0
Nickel	ppm	ASTM D5185m	>15	0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>25	0	0	<1
Lead	ppm	ASTM D5185m	>100	0	<1	1
Copper	ppm	ASTM D5185m	>200	6	1	5
Tin	ppm	ASTM D5185m	>25	0	0	0
Antimony	ppm	ASTM D5185m	>5		0	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	1	<1
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	<1	<1
Manganese	ppm	ASTM D5185m		<1	<1	<1
Magnesium	ppm	ASTM D5185m	90	24	6	65
Calcium	ppm	ASTM D5185m		9	0	3
Phosphorus	ppm	ASTM D5185m		18	32	46
Zinc	ppm	ASTM D5185m		11	4	4
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	27	<1	2
Sodium	ppm	ASTM D5185m		0	0	2
Potassium	ppm	ASTM D5185m	>20	0	2	3
Water	%	ASTM D6304	>0.2	0.004	▲ 0.269	0.024
ppm Water	ppm	ASTM D6304	>2000	48.8	△ 2690	240
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.25	0.53	0.232	0.439




OIL ANALYSIS REPORT










Bottom













Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** Test Package : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : RP0027474 : 05928386 : 10608333

To discuss this sample report, contact Customer Service at 1-800-237-1369.

Received Diagnosed Diagnostician

: 18 Aug 2023 : 21 Aug 2023 : Don Baldridge

1000 TIDAL ROAD DEER PARK, TX US 77536 Contact: CHARLES LOVE

OXY VINYLS DEER PARK PVC

charles_love@oxy.com T: (281)476-2277

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (281)476-2604

history2

LIGHT

NONE

NONE

NONE

NORML

history2

history2

NEG

141.7