

PROBLEM SUMMARY

Area [212198]


SEABRIGHT ACCURATE 2-YARD 03108234REM - MEDIFAST


Hydraulic System

NOT GIVEN (--- GAL)









RECOMMENDATION

We advise that you check for the source of water entry. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition. There is too much water present in this sample to perform a particle count.

PROBLEMATIC TEST RESULTS								
Sample Status				SEVERE				
Iron	ppm	ASTM D5185m	>20	<u>^</u> 25				
Water	%	ASTM D6304	>0.1	4.89				
ppm Water	ppm	ASTM D6304	>1000	48900				
Silt	scalar	*Visual	NONE	MODER				
Appearance	scalar	*Visual	NORML	▲ MILKY				
Emulsified Water	scalar	*Visual	>0.1	0.2%				

Customer Id: ADVFRA Sample No.: WC0836593 Lab Number: 05934290 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Fluid			?	Oil and filter change at the time of sampling has been noted.		
Change Filter			?	Oil and filter change at the time of sampling has been noted.		
Resample			?	We recommend an early resample to monitor this condition.		
Check Water Access			?	We advise that you check for the source of water entry.		

HISTORICAL DIAGNOSIS




OIL ANALYSIS REPORT

Area [212198]

SEABRIGHT ACCURATE 2-YARD 03108234REM - MEDIFAST

Hydraulic System

NOT GIVEN (--- GAL)





DIAGNOSIS

Recommendation

We advise that you check for the source of water entry. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition. There is too much water present in this sample to perform a particle count.

The iron level is abnormal. All other component wear rates are normal.

Contamination

Moderate concentration of visible dirt/debris present in the oil. There is a high concentration of water present in the oil.

Fluid Condition

The AN level is acceptable for this fluid.

				Aug2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0836593		
Sample Date		Client Info		21 Aug 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		Changed		
Sample Status				SEVERE		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	<u>^</u> 25		
Chromium	ppm	ASTM D5185m	>10	1		
Nickel	ppm	ASTM D5185m	>10	1		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		2		
Aluminum	ppm	ASTM D5185m	>10	0		
Lead	ppm	ASTM D5185m	>10	2		
Copper	ppm	ASTM D5185m	>75	3		
Tin	ppm	ASTM D5185m	>10	<1		
Vanadium	ppm	ASTM D5185m		<1		
Cadmium	ppm	ASTM D5185m		2		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		34		
Barium	ppm	ASTM D5185m		10		
Molybdenum	ppm	ASTM D5185m		<1		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m		17		
Calcium	ppm	ASTM D5185m		58		
Phosphorus	ppm	ASTM D5185m		228		
Zinc	ppm	ASTM D5185m		234		
Sulfur	ppm	ASTM D5185m		821		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	3		
Sodium	ppm	ASTM D5185m		8		
Potassium	ppm	ASTM D5185m	>20	2		
Water	%	ASTM D6304	>0.1	4.89		
ppm Water	ppm	ASTM D6304	>1000	48900		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2


0.55

Acid Number (AN)

mg KOH/g ASTM D8045



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: WC0836593 : 05934290

: 10619561

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 24 Aug 2023 Diagnosed

: 28 Aug 2023 Diagnostician : Don Baldridge

Test Package : IND 2 (Additional Tests: KF)

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

ADVANCED EQUIPMENT SALES

535 HAGEY RD SOUDERTON, PA US 18964

Contact: JEFF BURNLEY jburnley@aesales.net

> T: (215)723-7200 F: (215)723-7201