


PROBLEM SUMMARY


SCHTRUCK Machine Id 6240 [SCHTRUCK]


Diesel Engine

PETRO CANADA DURON SHP 15W40 (--- GAL)









RECOMMENDATION

The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS								
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL		
Fuel	%	ASTM D3524	>5	△ 6.7	△ 7.9	△ 6.9		
Visc @ 100°C	cSt	ASTM D445	15.4	12.1	△ 11.7	△ 11.6		

Customer Id: SCHPLA Sample No.: SBP0005615 Lab Number: 05958975 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Resample			?	We recommend an early resample to monitor this condition.

HISTORICAL DIAGNOSIS

03 Apr 2023 Diag: Wes Davis

FUEL



The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. All component wear rates are normal. There is a moderate amount of fuel present in the oil. Tests confirm the presence of fuel in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.



31 Jan 2023 Diag: Don Baldridge

FUEL



We advise that you check the fuel injection system. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is a moderate amount of fuel present in the oil. Fuel is present in the oil and is lowering the viscosity. The BN result indicates that there is suitable alkalinity remaining in the oil.



30 Mar 2021 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.






OIL ANALYSIS REPORT

SCHTRUCK 6240 [SCHTRUCK]

Diesel Engine

PETRO CANADA DURON SHP 15W40 (--- GAL)





DIAGNOSIS

Recommendation

The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

All component wear rates are normal.

Contamination

There is a moderate amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.


Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.

	Mw2021 Mw2021 Jun2023 4pv2023 Sep2023					
SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		SBP0005615	SBP0004203	SBP0002525
Sample Date		Client Info		14 Sep 2023	03 Apr 2023	31 Jan 2023
Machine Age	mls	Client Info		806498	784014	756940
Oil Age	mls	Client Info		22484	27574	26287
Oil Changed		Client Info		Changed	Changed	Changed
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
CONTAMINATION	I	method	limit/base	current	history1	history2
Glycol		WC Method		NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>80	26	31	38
Chromium	ppm	ASTM D5185m	>5	2	2	2
Nickel	ppm	ASTM D5185m	>2	0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m	>3	0	0	0
Aluminum	ppm	ASTM D5185m	>30	0	<1	0
Lead	ppm	ASTM D5185m	>30	<1	1	9
Copper	ppm	ASTM D5185m	>150	1	1	1
Tin	ppm	ASTM D5185m	>5	<1	0	<1
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	1	7	26
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	60	58	59	40
Manganese	ppm	ASTM D5185m	0	<1	1	<1
Magnesium	ppm	ASTM D5185m	1010	960	879	487
Calcium	ppm	ASTM D5185m	1070	1074	1161	1383
Phosphorus	ppm	ASTM D5185m	1150	992	970	640
Zinc	ppm	ASTM D5185m	1270	1217	1166	812
Sulfur	ppm	ASTM D5185m	2060	3438	3383	2336
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	2	3	4
Sodium	ppm	ASTM D5185m		8	9	9
Potassium	ppm	ASTM D5185m	>20	2	4	2
Chlorine	ppm	ASTM D5185m				
Fuel	%	ASTM D3524	>5	△ 6.7	▲ 7.9	△ 6.9
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	2.1	1.9	1.7
Nitration	Abs/cm	*ASTM D7624	>20	9.7	10.6	11.9
Sulfation	Abs/.1mm	*ASTM D7415	>30	23.6	26.0	28.3
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	18.7	24.1	31.5
Base Number (BN)	mg KOH/g	ASTM D2896		6.7	6.3	5.4
	9 9					



OIL ANALYSIS REPORT




VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERTIES		method	limit/base	current	history1	history2

12.1

11.7


11.6


Visc @ 100°C **GRAPHS**




cSt

ASTM D445 15.4











Laboratory Sample No. Lab Number Unique Number : 10660188

: 05958975

: SBP0005615

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received Diagnosed

: 22 Sep 2023 : 26 Sep 2023 Diagnostician : Wes Davis

Test Package : FLEET (Additional Tests: PercentFuel) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

SCHMIDT TRANSPORTATION - 605449

108 E Bay Road Plattsmouth, NE US 68048 Contact: NICK DOTY

doty@liquidtrucking.com

T: (402)949-9398

Submitted By: CASEY WILKIE