


PROBLEM SUMMARY

VILTER B37157 - HC5

Compressor Fluid

PETRO CANADA REFLO XL SYNTHETIC BLEND (110 GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS							
Sample Status			ATTENTION	ABNORMAL	SEVERE		
Particles >4µm	ASTM D7647	>10000	<u> </u>		2905		
Particles >6µm	ASTM D7647	>2500	4092		792		
Oil Cleanliness	ISO 4406 (c)	>20/18/15	<u> </u>		19/17/13		


Customer Id: ROCROCUS Sample No.: WC0814208 Lab Number: 05962250 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Don Baldridge +1 <u>don.b505@comcast.net</u>

To change component or sample information: Customer Service +1 1-800-237-1369 <u>customerservice@wearcheck.com</u>



There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

30 Jul 2023 Diag: Jonathan Hester

DEGRADATION

o Jul 2023 Diag: Johathan Hest

We recommend that you drain the oil and perform a filter service on this component if not already done. We recommend an early resample to monitor this condition. We were unable to perform a particle count due to a high concentration of particles present in this sample. The aluminum level is abnormal. All other component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. The AN level is at the top-end of the recommended limit.

29 Jul 2023 Diag: Jonathan Hester

DEGRADATION



We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition.All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. The oil viscosity is higher than normal. The AN level is above the recommended limit.




view repor

22 Jun 2023 Diag: Don Baldridge

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is a moderate amount of silt (particulates < 6 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.







OIL ANALYSIS REPORT

VILTER B37157 - HC5

Compressor

PETRO CANADA REFLO XL SYNTHETIC BLEND (110 GAL)

DIAGNOSIS

A Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

Wear


All component wear rates are normal.

Contamination

There is a moderate amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0814208	WC0820545	WC0820501
Sample Date		Client Info		18 Sep 2023	30 Jul 2023	29 Jul 2023
Machine Age	hrs	Client Info		81309	0	49115
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	Not Changd	N/A
Sample Status				ATTENTION	ABNORMAL	SEVERE
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	6	<1	0
Chromium	ppm	ASTM D5185m	>5	0	0	0
Nickel	ppm	ASTM D5185m		0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>15	0	▲ 15	1
Lead	ppm	ASTM D5185m	>65	0	0	0
Copper	ppm	ASTM D5185m		۰ <1	<1	1
Tin	ppm	ASTM D5185m	>10	0	0	0
Vanadium	ppm	ASTM D5185m	>10	0	<1	<1
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES	PP	method	limit/base	current	history1	history2
			in in base			
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		<1	<1	<1
Magnesium	ppm	ASTM D5185m		0	0	0
Calcium	ppm	ASTM D5185m		2	0	0
Phosphorus	ppm	ASTM D5185m		0	200	113
Zinc	ppm	ASTM D5185m		<1	0	0
Sulfur	ppm	ASTM D5185m		1215	404	284
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>35	<1	6	2
Sodium	ppm	ASTM D5185m		2	<1	2
Potassium	ppm	ASTM D5185m	>20	0	0	0
Water	%	ASTM D6304	>0.1	0.00		
ppm Water	ppm	ASTM D6304	>1000	0.00		
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>10000	1 3904		2905
Particles >6µm		ASTM D7647	>2500	<u> </u>		792
Particles >14µm		ASTM D7647	>320	128		45
Particles >21µm		ASTM D7647	>80	20		7
Particles >38µm		ASTM D7647	>20	0		0
Particles >71µm		ASTM D7647		0		0
Oil Cleanliness		ISO 4406 (c)	>20/18/15	21/19/14		19/17/13
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.1	0.014	▲ 1.33	4.25


Contact/Location: JAY BURKE - ROCROCUS




OIL ANALYSIS REPORT











Certificate L2367

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	A MODER	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.1	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	FIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	59.3	57.8	45.5	52.8
SAMPLE IMAGE	S	method	limit/base	current	history1	history2
Color						



Bottom





To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: JAY BURKE - ROCROCUS

jfburke@hormel.com

T: (815)562-4141

F: (815)562-4147