


PROBLEM SUMMARY


{UNASSIGNED} 510-2675-1110 TFL Board Turner

Component **Gear Reducer**

GEAR OIL (PAG) ISO 460 (--- GAL)



COMPONENT CONDITION SUMMARY



RECOMMENDATION

Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS									
Sample Status			ATTENTION						
Visc @ 40°C	cSt	ASTM D445	460	△ 233					

Customer Id: ARAGRAUS Sample No.: WC0824128 Lab Number: 05963556 Test Package: PLANT To manage this report scan the QR code To discuss the diagnosis or test data: Don Baldridge +1 don.b505@comcast.net To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

Area {UNASSIGNED} 510-2675-1110 TFL Board Turner

Gear Reducer

GEAR OIL (PAG) ISO 460 (--- GAL)

Sample Rating Trend



DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil.


▲ Fluid Condition

Viscosity of sample indicates oil is within ISO 220 range, advise investigate. Confirm oil type. The AN level is acceptable for this fluid.

				Sep2023		
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0824128		
Sample Date		Client Info		22 Sep 2023		
Machine Age	yrs	Client Info		5		
Oil Age	yrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ATTENTION		
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184		15		
Iron	ppm	ASTM D5185m	>150	<1		
Chromium	ppm	ASTM D5185m	>10	0		
Nickel	ppm	ASTM D5185m	>10	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	<1		
Lead	ppm	ASTM D5185m	>100	0		
Copper	ppm	ASTM D5185m	>50	8		
Tin	ppm	ASTM D5185m	>10	0		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	5	0		
Barium	ppm	ASTM D5185m	5	0		
Molybdenum	ppm	ASTM D5185m	5	0		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m	5	0		
Calcium	ppm	ASTM D5185m	5	0		
Phosphorus	ppm	ASTM D5185m	775	473		
Zinc	ppm	ASTM D5185m	5	0		
Sulfur	ppm	ASTM D5185m	2000	2127		
CONTAMINANTS		method	limit/base	ourront.	historyt	history
				current	history1	history2
Silicon	ppm	ASTM D5185m	>50	17		
Sodium	ppm	ASTM D5185m		<1		
Potassium	ppm	ASTM D5185m	>20	0		
Water	%	ASTM D6304		0.001		
ppm Water	ppm	ASTM D6304	>1000	5.6		
FLUID CLEANLI	NESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>20000	4707		
Particles >6µm		ASTM D7647	>5000	383		
Particles >14μm		ASTM D7647	>640	17		
Particles >21µm		ASTM D7647	>160	5		
Particles >38μm		ASTM D7647	>40	0		
Particles >71µm		ASTM D7647	>10	0		
Oil Cleanliness		ISO 4406 (c)	>21/19/16	19/16/11		
FLUID DEGRAD	ATION	method	limit/base	current	history1	history2



OIL ANALYSIS REPORT





Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

Test Package

: WC0824128 Received : 05963556 Diagnosed : 10670107

: 28 Sep 2023 : 29 Sep 2023 : Don Baldridge Diagnostician

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

: PLANT

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

5851 ARAUCO ROAD GRAYLING, MI

US 49738 Contact: JOSEPH GREEN

joseph.green@arauco.com T:

F: