

## **PROBLEM SUMMARY**

Sample Rating Trend

**WATER** 

COX SM239D-QTRS


Component **Swing Drive** 

**CHEVRON MEROPA 220 (--- GAL)** 





## COMPONENT CONDITION SUMMARY



### **RECOMMENDATION**

We advise that you check for the source of water entry. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

PROBLEMATIC T	EST RE	SULTS			
Sample Status				SEVERE	 
Water	%	ASTM D6304	>0.2	<b>△</b> 0.849	 
ppm Water	ppm	ASTM D6304	>2000	<b>A</b> 8490	 
Appearance	scalar	*Visual	NORML	▲ MILKY	 
Free Water	scalar	*Visual		<b>1.0</b>	 

**Customer Id: SEALAF** Sample No.: WC0825789 Lab Number: 05964757 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 ihester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Fluid			?	Oil and filter change at the time of sampling has been noted.		
Change Filter			?	Oil and filter change at the time of sampling has been noted.		
Resample			?	We recommend an early resample to monitor this condition.		
Check Water Access			?	We advise that you check for the source of water entry.		

## HISTORICAL DIAGNOSIS




## **OIL ANALYSIS REPORT**

# **COX SM239D-QTRS**

Component

**Swing Drive** 

CHEVRON MEROPA 220 (--- GAL)





## DIAGNOSIS

#### Recommendation

We advise that you check for the source of water entry. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

#### Wear

All component wear rates are normal.

### Contamination

Appearance is milky. Free water present. There is a high concentration of water present in the oil.


#### **Fluid Condition**

The AN level is acceptable for this fluid.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0825789		
Sample Date		Client Info		11 Sep 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		Changed		
Sample Status				SEVERE		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>400	41		
Chromium	ppm	ASTM D5185m	>10	0		
Nickel	ppm	ASTM D5185m	>10	0		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	2		
Lead	ppm	ASTM D5185m	>50	0		
Copper	ppm	ASTM D5185m	>200	2		
Tin	ppm	ASTM D5185m	>10	<1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
				•		
ADDITIVES		method	limit/base	current	history1	history2
ADDITIVES Boron	ppm	method ASTM D5185m	limit/base		history1	history2
				current	•	
Boron	ppm	ASTM D5185m		current 3		
Boron Barium	ppm	ASTM D5185m ASTM D5185m		current 3 0		
Boron Barium Molybdenum	ppm ppm	ASTM D5185m ASTM D5185m ASTM D5185m		current 3 0		
Boron Barium Molybdenum Manganese	ppm ppm ppm	ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m		current 3 0 0 <		
Boron Barium Molybdenum Manganese Magnesium	ppm ppm ppm ppm	ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m		current 3 0 0 <		
Boron Barium Molybdenum Manganese Magnesium Calcium	ppm ppm ppm ppm ppm	ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	40	current 3 0 0 <-1 0 0		
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus	ppm ppm ppm ppm ppm ppm	ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	40	current 3 0 0 <-1 0 247		
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc	ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	270	current 3 0 0 <-1 0 247 0		
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur	ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	270 8600	current 3 0 0		
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur CONTAMINANTS	ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185m	270 8600 limit/base	current  3 0 0 0 <1 0 247 0 8735 current	history1	    history2
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur CONTAMINANTS	ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185m	270 8600 limit/base	current  3 0 0 0 <1 0 247 0 8735  current	    history1	history2
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur CONTAMINANTS Silicon Sodium	ppm ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185m	270 8600 limit/base	current  3 0 0 0 <1 0 247 0 8735  current 1 <1	    history1	history2
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur CONTAMINANTS Silicon Sodium Potassium	ppm ppm ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185m	270 8600 limit/base >50 >20	current  3 0 0 0 <1 0 247 0 8735  current 1 <1 0		history2
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur CONTAMINANTS Silicon Sodium Potassium Water	ppm ppm ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185m	270  8600  limit/base >50  >20 >0.2	current  3 0 0 0 <1 0 247 0 8735  current 1 <1 0 0 0.849		history2



## **OIL ANALYSIS REPORT**







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** 

: WC0825789

: 05964757 : 10671308

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received Diagnosed

: 03 Oct 2023 : Jonathan Hester Diagnostician

: 29 Sep 2023

Test Package : IND 2 (Additional Tests: KF) To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) **SEATRAX INC** 

308 GALBERT ROAD LAFAYETTE, LA US 70506

Contact: TONY VALLERY tvallery@seatrax.com

Contact/Location: TONY VALLERY - SEALAF

T: (337)706-7900 F: (337)706-7901