


PROBLEM SUMMARY

SULLUBE


SULLAIR 200703160116 - EPSILYTE J-ACP-B/PACK WAREHOUSE

Component

Compressor



COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend that you drain the oil from the component if this has not already been done. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS								
Sample Status				ATTENTION				
Acid Number (AN)	mg KOH/g	ASTM D8045	.06	2.05				

Customer Id: UCHTESTL Sample No.: UCH0596459 Lab Number: 05966459 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 ihester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Fluid			?	We recommend that you drain the oil from the component if this has not already been done.			

HISTORICAL DIAGNOSIS




OIL ANALYSIS REPORT

SULLUBE SULLAIR 200703160116 - EPSILYTE J-ACP-B/PACK WAREHOUSE

Component

Compressor





DIAGNOSIS

Recommendation

We recommend that you drain the oil from the component if this has not already been done. Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil.


Fluid Condition

The AN level is above the recommended limit.

		1		Sep2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		UCH0596459		
Sample Date		Client Info		12 Sep 2023		
Machine Age	hrs	Client Info		75637		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		Not Changd		
Sample Status				ATTENTION		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	0		
Chromium	ppm	ASTM D5185m	>10	0		
Nickel	ppm	ASTM D5185m		0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	<1		
Lead	ppm	ASTM D5185m	>25	<1		
Copper	ppm	ASTM D5185m	>50	<1		
Tin	ppm	ASTM D5185m	>15	<1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m	745	207		
Molybdenum	ppm	ASTM D5185m	0.0	0		
Manganese	ppm	ASTM D5185m		0		
Magnesium	ppm	ASTM D5185m	0.0	0		
Calcium	ppm	ASTM D5185m	1	<1		
Phosphorus	ppm	ASTM D5185m	3	9		
Zinc	ppm	ASTM D5185m	0.1	0		
Sulfur	ppm	ASTM D5185m	240	379		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	3		
Sodium	ppm	ASTM D5185m		76		
Potassium	ppm	ASTM D5185m	>20	9		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	.06	2.05		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.1	NEG		
Free Water	scalar	*Visual		NEG		
1.52.27\ Rov. 1				Contact/Locatio	n: DON BIDDEI	LUCHTECTI



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 10673010

: UCH0596459 : 05966459

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 02 Oct 2023

Diagnosed : 04 Oct 2023 Diagnostician : Jonathan Hester

Test Package : IND 2 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) **HTE TECHNOLOGIES**

2021 CONGRESSIONAL DR ST LOUIS, MO US 63146

Contact: DON RIDDELL don.riddell@htetech.com

F: (314)731-4424

Contact/Location: DON RIDDELL - UCHTESTL