

PROBLEM SUMMARY

Sample Rating Trend

ct2008 Dec2010 Nov2011 Feb2016 Jun/2017 May/018 Jun/0701 Sear/0721 Sear/

WEAR






OKLAHOMA/102/EG - OTHER SERVICE
78.66 [OKLAHOMA^102^EG - OTHER SERVICE]

Transmission (Manual)

MOBIL DELVAC 1330 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor. (Customer Sample Comment: 16744 hrs)

PROBLEMATIC TEST RESULTS								
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL		
Aluminum	ppm	ASTM D5185m	>25	△ 35	△ 39	A 34		

Customer Id: SHEWIC Sample No.: WC0819820 Lab Number: 05969370 Test Package: CONST



To manage this report scan the QR code

To discuss the diagnosis or test data: Sean Felton +1 919-379-4092 sfelton@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

04 Jun 2022 Diag: Don Baldridge

WEAR



No corrective action is recommended at this time. Resample at the next service interval to monitor. The aluminum level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



21 Feb 2022 Diag: Jonathan Hester

WEAR



No corrective action is recommended at this time. Resample at the next service interval to monitor. The aluminum level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



17 Sep 2021 Diag: Don Baldridge

NORMAL




Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.





OIL ANALYSIS REPORT




78.66 [OKLAHOMA^102^EG - OTHER SERVICE]



Transmission (Manual)

MOBIL DELVAC 1330 (--- GAL)





DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor. (Customer Sample Comment: 16744 hrs)

Wear

The aluminum level is abnormal. All other component wear rates are normal.

Contamination

There is no indication of any contamination in the fluid


Fluid Condition


The condition of the fluid is acceptable for the time in service.

(GAL)		ct2008 Dec20	10 Nov2011 Feb2016	Jun2017 May2018 Jul2020 Sep	2021 Sep202	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0819820	WC0649272	WC0649291
Sample Date		Client Info		27 Sep 2023	04 Jun 2022	21 Feb 2022
Machine Age	hrs	Client Info		16744	15780	15280
Oil Age	hrs	Client Info		14254	14254	14254
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	37	41	25
Chromium	ppm	ASTM D5185m	>5	0	<1	<1
Nickel	ppm	ASTM D5185m	>5	0	0	0
Titanium	ppm	ASTM D5185m		0	<1	0
Silver	ppm	ASTM D5185m	>7	0	<1	0
Aluminum	ppm	ASTM D5185m	>25	△ 35	△ 39	A 34
Lead	ppm	ASTM D5185m	>45	<1	<1	<1
Copper	ppm	ASTM D5185m	>225	85	71	35
Tin	ppm	ASTM D5185m	>10	<1	<1	<1
Antimony	ppm	ASTM D5185m				<1
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		31	46	35
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		<1	<1	<1
Manganese	ppm	ASTM D5185m		3	3	2
Magnesium	ppm	ASTM D5185m		17	16	14
Calcium	ppm	ASTM D5185m		2956	3111	3150
Phosphorus	ppm	ASTM D5185m		1066	1112	1073
Zinc	ppm	ASTM D5185m		1288	1238	1153
Sulfur	ppm	ASTM D5185m		5710	5599	4898
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>125	8	17	8
Sodium	ppm	ASTM D5185m		4	7	4
Potassium	ppm	ASTM D5185m	>20	0	0	0
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.1	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG




OIL ANALYSIS REPORT







FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	102	98.5	99.7	102
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image
CDADUC						

GRAPHS











Certificate L2367

Laboratory Sample No. Lab Number

Unique Number : 10675921 Test Package : CONST

: WC0819820 : 05969370

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 04 Oct 2023 Diagnosed : 06 Oct 2023

Diagnostician : Sean Felton

To discuss this sample report, contact Customer Service at 1-800-237-1369.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

SHERWOOD CONSTRUCTION CO INC

3219 WEST MAY ST WICHITA, KS US 67213

Contact: JIMMY DERAMUS jimmy.deramus@sherwood.net

> T: (918)691-3306 F: x:

Report Id: SHEWIC [WUSCAR] 05969370 (Generated: 10/20/2023 12:07:58) Rev: 1