
PROBLEM SUMMARY

Area WHEY [1857677] Machine Id PO02PP21BB01 Component

IEA

Bearing Fluid MOBIL SHC 626 (--- QTS)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS							
Sample Status				ATTENTION	NORMAL	ABNORMAL	
Visc @ 40°C	cSt	ASTM D445	69.9	<u> </u>	67.3	67.7	


Customer Id: LEPGRE Sample No.: WC0864075 Lab Number: 05996126 Test Package: IND 1



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 <u>customerservice@wearcheck.com</u>



RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

22 Apr 2020 Diag: Don Baldridge



Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

view report

view report

23 Oct 2019 Diag: Jonathan Hester



We advise that you check for the source of water entry. We advise that you follow the water drain-off procedure for this component. Resample at the next service interval to monitor All component wear rates are normal. Free water present. The condition of the oil is acceptable for the time in service.

21 Apr 2019 Diag: Angela Borella



No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is suitable for further service.







OIL ANALYSIS REPORT

Area WHEY [1857677] Machine Id PO02PP21BB01 Component

Bearing Fluid MOBIL SHC 626 (--- QTS)

DIAGNOSIS

A Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

Wear


All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil.

Fluid Condition


The oil viscosity is higher than normal. Confirm oil type.




SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0864075	WC0458072	WC0390163
Sample Date		Client Info		24 Oct 2023	22 Apr 2020	23 Oct 2019
Machine Age	mths	Client Info		0	0	0
Oil Age	mths	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ATTENTION	NORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	0	1	1
Chromium	ppm	ASTM D5185m	>20	0	0	0
Nickel	ppm	ASTM D5185m	>20	0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>20	0	<1	<1
Lead	ppm	ASTM D5185m		0	0	0
Copper	ppm	ASTM D5185m		0	<1	<1
Tin	ppm	ASTM D5185m	>20	0	0	0
Antimony	ppm	ASTM D5185m	-		0	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	<1	0
Barium	ppm	ASTM D5185m		<1	0	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		0	0	<1
Magnesium	ppm	ASTM D5185m		۲ ح1	0	<1
Calcium	ppm	ASTM D5185m		1	0	0
Phosphorus	ppm	ASTM D5185m		430	445	445
Zinc	ppm	ASTM D5185m		4	2	0
Sulfur	ppm	ASTM D5185m		22	32	29
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	0	<1	<1
Sodium	ppm	ASTM D5185m		0	0	0
Potassium	ppm	ASTM D5185m	>20	0	0	0
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	LAYRD
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>2	NEG	NEG	0.2%
Free Water	scalar	*Visual		NEG	NEG	▲ 2.0



OIL ANALYSIS REPORT



FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	69.9	<mark> </mark> 89.68	67.3	67.7
SAMPLE IMAC	GES	method	limit/base	current	history1	history2
Color				•		
Bottom						



LEPRINO FOODS-GREELEY 1302 1ST AVE GREELEY, CO US 80631-5909 Contact: ERIC KLINE EKLINE@LEPRINOFOODS.COM T: *SM 106:2012)* F: (970)347-5190



 Certificate 12367
 Test Package
 : IND 1

 To discuss this sample report, contact Customer Service at 1-800-237-1369.
 EKLIN

 * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.
 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Submitted By: MICHAEL VILLASENOR

Page 4 of 4