

# **FUEL REPORT**

Sample Rating Trend


NORMAL

Machine Id **0712142360 - TRAILER 98 0712142360 - TRAILER 98** 

Component

Diesel Fuel
Fluid

NOT GIVEN (--- GAL)



### Recommendation

This is a baseline read-out on the submitted sample.

hrs	method Client Info Client Info	limit/base	current WC0834322	history1	history2
hrs	Client Info		WC0834322		
hrs					
hrs			27 Sep 2023		
	Client Info		195		
			NORMAL		
Т	method	limit/base	current	history1	history2
ppm	ASTM D5185m		57		
	method	limit/base	current	history1	history2
ppm	ASTM D5185m	<1.0	0		
ppm	ASTM D5185m	<0.1	<1		
ppm	ASTM D5185m	<0.1	0		
	method	limit/base	current	history1	history2
ppm	ASTM D5185m	<0.1	0		
ppm	ASTM D5185m	<0.1	0		
ppm	ASTM D5185m	< 0.1	0		
ppm	ASTM D5185m	<0.1	0		
ppm	ASTM D5185m	< 0.1	0		
ppm	ASTM D5185m	<0.1	2		
ppm	ASTM D5185m	< 0.1	0		
ppm	ASTM D5185m	<0.1	<1		
ppm	ASTM D5185m	<0.1	0		
	method	limit/base	current	history1	history2
				no image	no image
			0	no image	no image
	opm	opm         ASTM D5185m           method           opm         ASTM D5185m           opm         ASTM D5185m	method         limit/base           opm         ASTM D5185m         <1.0           opm         ASTM D5185m         <0.1           opm         ASTM D5185m         <0.1	Method   limit/base   current	Method   limit/base   current   history1



## **FUEL REPORT**



Certificate L2367

Laboratory Sample No. Lab Number

: WC0834322 : 06006633 Unique Number : 10740395 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 13 Nov 2023 Received : 16 Nov 2023 Diagnosed Diagnostician : Jonathan Hester

To discuss this sample report, contact Customer Service at 1-800-237-1369.

joe@gentechltd.com \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (845)568-0500 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (845)568-3073

**GEN TECH LTD** 

NEW WINDSOR, NY

Contact: JOE SAYEGH

3017 RT 9W

US 12553