

FUEL REPORT

Sample Rating Trend

NORMAL

WESTCHESTER DEF - MILL ST

Component

Diesel Fuel
Fluid

NOT GIVEN (--- GAL)

DIAGNOSIS


Recommendation


This is a baseline read-out on the submitted sample.

		Nov2019	Nov2020	Dec2021 Oct2022	Nov2023	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0834447	WC0699389	WC0651532
Sample Date		Client Info		12 Nov 2023	11 Oct 2022	08 Dec 2021
Machine Age	hrs	Client Info		0	369	0
Sample Status				NORMAL	NORMAL	ABNORMAL
SULFUR CONTE	NΤ	method	limit/base	current	history1	history2
Sulfur	ppm	ASTM D5185m		0	6	0
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	<1.0	0	0	0
Sodium	ppm	ASTM D5185m	< 0.1	<1	0	0
Potassium	ppm	ASTM D5185m	<0.1	0	0	0
HEAVY METALS		method	limit/base	current	history1	history2
Aluminum	ppm	ASTM D5185m	< 0.1	0	0	<1
Nickel	ppm	ASTM D5185m	< 0.1	0	0	0
Lead	ppm	ASTM D5185m	< 0.1	0	0	0
Vanadium	ppm	ASTM D5185m	< 0.1	0	0	0
Iron	ppm	ASTM D5185m	< 0.1	0	0	<1
Calcium	ppm	ASTM D5185m	< 0.1	0	<1	0
Magnesium	ppm	ASTM D5185m	< 0.1	0	0	0
Phosphorus	ppm	ASTM D5185m	<0.1	<1	0	0
Zinc	ppm	ASTM D5185m	<0.1	0	0	0
SAMPLE IMAGES	6	method	limit/base	current	history1	history2
Color					A499359	6.1
Bottom						



FUEL REPORT







Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 10740407 Test Package : MOB 1

: WC0834447 : 06006645 To discuss this sample report, contact Customer Service at 1-800-237-1369.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 13 Nov 2023 Diagnosed Diagnostician : Jonathan Hester

: 16 Nov 2023

3017 RT 9W NEW WINDSOR, NY US 12553 Contact: JOE SAYEGH joe@gentechltd.com T: (845)568-0500

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (845)568-3073

GEN TECH LTD