

FUEL REPORT

Sample Rating Trend

NORMAL



ROUTE 202 PUMP STATION 0671533

Component

Diesel Fuel
Fluid

NOT GIVEN (--- GAL)

Recommendation

This is a baseline read-out on the submitted sample.

ATION	method	limit/base	current	history1	history2
	Client Info		WC0834504		
	Client Info		05 Oct 2023		
hrs	Client Info		670		
			NORMAL		
I T	method	limit/base	current	history1	history2
ppm	ASTM D5185m		0		
	method	limit/base	current	history1	history2
ppm	ASTM D5185m	<1.0	0		
ppm	ASTM D5185m	<0.1	<1		
ppm	ASTM D5185m	<0.1	0		
	method	limit/base	current	history1	history2
ppm	ASTM D5185m	< 0.1	0		
ppm	ASTM D5185m	<0.1	0		
ppm	ASTM D5185m	< 0.1	0		
ppm	ASTM D5185m	<0.1	0		
ppm	ASTM D5185m	< 0.1	0		
ppm	ASTM D5185m	<0.1	0		
ppm	ASTM D5185m	< 0.1	0		
ppm	ASTM D5185m	<0.1	<1		
ppm	ASTM D5185m	< 0.1	0		
	method	limit/base	current	history1	history2
				no image	no image
			(re)	no image	no image
	ppm	Client Info Client Info Client Info Client Info Client Info MT Method PPM ASTM D5185m PPM ASTM D5185m PPM ASTM D5185m Method PPM ASTM D5185m PPM ASTM D5185m	Client Info Client Info	Client Info	Client Info



FUEL REPORT



Certificate L2367

Laboratory Sample No. Lab Number

: WC0834504 : 06006647 Unique Number : 10740409 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 13 Nov 2023 Received : 16 Nov 2023 Diagnosed Diagnostician : Jonathan Hester

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: (845)568-0500 F: (845)568-3073

GEN TECH LTD

NEW WINDSOR, NY

joe@gentechltd.com

Contact: JOE SAYEGH

3017 RT 9W

US 12553