


PROBLEM SUMMARY

KAESER AS 25T 5981545 (S/N 1013)

Compressor Fluid

KAESER SIGMA (OEM) S-460 (--- LTR)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS Sample Status ABNORMAL ABNORMAL ABNORMAL Particles >6µm ASTM D7647 >1300 **1778 A** 8601 Particles >14µm ASTM D7647 >80 🔺 174 692 Particles >21µm ASTM D7647 >20 56 **1**56 **Oil Cleanliness** ISO 4406 (c) >--/17/13 **20/18/15** 22/20/17


Customer Id: AKIWIN Sample No.: KC06007740 Lab Number: 06007740 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com



There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

17 Jul 2023 Diag: Don Baldridge

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

17 Mar 2023 Diag: Don Baldridge

The filter change at the time of sampling has been noted. We were unable to perform a particle count due to a high concentration of particles present in this sample. We advise that you stop the unit and follow the water drainoff procedure for this component. We recommend an early resample in 500 hours to monitor this condition.All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. There is a light concentration of water present in the oil. The AN level is acceptable for this fluid.

view report



05 Dec 2022 Diag: Jonathan Hester

The filter change at the time of sampling has been noted. We advise that you stop the unit and follow the water drain-off procedure for this component. We recommend an early resample in 500 hours to monitor this condition.All component wear rates are normal. Free water present. There is a high concentration of water present in the oil. The amount and size of particulates present in the system are acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.







OIL ANALYSIS REPORT

KAESER AS 25T 5981545 (S/N 1013)

Compressor

KAESER SIGMA (OEM) S-460 (--- LTR)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

Wear


All component wear rates are normal.

Contamination

There is a high amount of particulates present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



SAMPLE INFORM	ATION	method	limit/base	current	history1	history2
Sample Number		Client Info		KC06007740	KC05909482	KC05813930
Sample Date		Client Info		31 Oct 2023	17 Jul 2023	17 Mar 2023
Machine Age	hrs	Client Info		33985	32139	29932
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	0	0	0
Chromium	ppm	ASTM D5185m	>10	0	0	0
Nickel	ppm	ASTM D5185m	>3	0	0	0
Titanium	ppm	ASTM D5185m	>3	<1	0	0
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>10	0	0	<1
Lead	ppm	ASTM D5185m		0	0	0
Copper	ppm	ASTM D5185m		18	14	6
Tin	ppm	ASTM D5185m		0	0	0
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES	le le	method	limit/base	current	history1	history2
		ASTM D5185m			0	0
Boron	ppm		00	0		
Barium	ppm	ASTM D5185m	90	0	0	3
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m	0.0	0	0	<1
Magnesium	ppm	ASTM D5185m	90	0	14	52
Calcium	ppm	ASTM D5185m	2	0	0	3
Phosphorus	ppm	ASTM D5185m		0	7	6
Zinc	ppm	ASTM D5185m		0	20	29
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	0	<1	0
Sodium	ppm	ASTM D5185m		<1	4	11
Potassium	ppm	ASTM D5185m	>20	0	2	2
Water	%	ASTM D6304	>0.05	0.006	0.049	0.111
ppm Water	ppm	ASTM D6304	>500	60.8	490.2	▲ 1110
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647		5977	23506	
Particles >6µm		ASTM D7647	>1300	🔺 1778	A 8601	
Particles >14µm		ASTM D7647	>80	1 74	692	
Particles >21µm		ASTM D7647	>20	6	1 56	
Particles >38µm		ASTM D7647	>4	1	<u> </u>	
Particles >71µm		ASTM D7647	>3	0	0	
Oil Cleanliness		ISO 4406 (c)	>/17/13	20/18/15	▲ 22/20/17	
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.4	0.28	0.30	0.35



Acid Number


0.50


(^B/H0X Ē0.3


Water (ppm)


200

OIL ANALYSIS REPORT










Bottom



Contact/Location: ? ? - AKIWIN

Page 4 of 4