


Jul6/22

Jul5/23



RECOMMENDATION

EAS

622 AIRVAYOR

MOBIL SHC 630 (10 GAL)

Outboard Bearing

^{Area} **412**

Component

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS

Sample Status				ABNORMAL	ABNORMAL	ABNORMAL		
Silicon	ppm	ASTM D5185m	>15	<u> </u>	<u> </u>	4 4		
Particles >4µm		ASTM D7647	>10000	6 59764	2 0182	🔺 16639		
Particles >6µm		ASTM D7647	>2500	<u> </u>	1701	1209		
Oil Cleanliness		ISO 4406 (c)	>20/18/14	A 23/20/13	2 2/18/13	🔺 21/17/12		

Customer Id: BRIDES Sample No.: WC0838895 Lab Number: 06009528 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Don Baldridge +1 <u>don.b505@comcast.net</u>

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

05 Jul 2023 Diag: Angela Borella



The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of silt (particulates < 6 microns in size) present in the oil. Elemental level of silicon (Si) above normal indicating ingress of seal material. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

30 Dec 2022 Diag: Angela Borella

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. Elemental level of silicon (Si) above normal indicating ingress of seal material. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



view report



06 Jul 2022 Diag: Doug Bogart


The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of silt (particulates < 6 microns in size) present in the oil. Elemental level of silicon (Si) above normal indicating ingress of seal material. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend



622 AIRVAYOR Component Outboard Bearing Fluid MOBIL SHC 630 (10 GAL)

DIAGNOSIS

Area 412

Recommendation

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil. Elemental level of silicon (Si) above normal indicating ingress of seal material.


Fluid Condition


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.


SAMPLE INFURI	VIATION	method	iimi/base	current	riistory i	riistory2
Sample Number		Client Info		WC0838895	WC0569523	WC0640559
Sample Date		Client Info		10 Nov 2023	05 Jul 2023	30 Dec 2022
Machine Age	mths	Client Info		6	6	6
Oil Age	mths	Client Info		0	0	0
Oil Changed		Client Info		Changed	Changed	Changed
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184		7	7	16
Iron	ppm	ASTM D5185m	>20	4	2	2
Chromium	ppm	ASTM D5185m	>20	0	0	0
Nickel	ppm	ASTM D5185m	>20	0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>20	<1	<1	0
Lead	ppm	ASTM D5185m	>20	0	0	0
Copper	ppm	ASTM D5185m	>20	<1	0	0
Tin	ppm	ASTM D5185m	>20	2	0	2
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m		6	0	1
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		0	0	0
Magnesium	ppm	ASTM D5185m		<1	0	<1
Calcium	ppm	ASTM D5185m		2	0	0
Phosphorus	ppm	ASTM D5185m		432	471	455
Zinc	ppm	ASTM D5185m		3	<1	4
Sulfur	ppm	ASTM D5185m		0	0	0
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	A 35	5 3	🔺 44
Sodium	ppm	ASTM D5185m		0	0	0
Potassium	ppm	ASTM D5185m	>20	<1	<1	<1
FLUID CLEANLIN	NESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>10000	6 59764	2 0182	🔺 16639
Particles >6µm		ASTM D7647	>2500	<u> </u>	1701	1209
Particles >14µm		ASTM D7647	>160	60	42	31
Particles >21µm		ASTM D7647	>40	9	7	6
Particles >38µm		ASTM D7647	>10	1	1	1
Particles >71µm		ASTM D7647	>3	0	0	0
Oil Cleanliness		ISO 4406 (c)	>20/18/14	A 23/20/13	🔺 22/18/13	1 /17/12
FLUID DEGRAD	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.55	0.63	0.57



OIL ANALYSIS REPORT








200

190

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	217.7	217	219	220
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color						

Bottom



ul5/23 10/2/ Jec12/1 **BRIDGESTONE FIRESTONE - DES MOINES** Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513 Sample No. : WC0838895 Received : 16 Nov 2023 4600 NW 2ND AVE Lab Number : 06009528 DES MOINES, IA Diagnosed : 19 Nov 2023 Unique Number : 10743290 Diagnostician : Don Baldridge US 50313 Test Package : IND 2 (Additional Tests: PQ, PrtCount) Contact: SCOTT CARTER Certificate L2367 CarterScottA@FirestoneAg.com To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: x: F: x: Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)