

PROBLEM SUMMARY

Sample Rating Trend

VISCOSITY

VISCOSITY


Machine Id

11-1038 - JOHN DEERE EXCAVATOR

Component
Diesel Engine

PETRO CANADA DURON ADVANCED 10W30 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATIC T	EST RE	SULTS			
Sample Status				ATTENTION	
Visc @ 100°C	cSt	ASTM D445	10.3	14.6	

Customer Id: CONLINNE
Sample No.: SBP0004945
Lab Number: 06010112
Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data:
Don Baldridge +1
don.b505@comcast.net

To change component or sample information:
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Fluid			?	Oil and filter change at the time of sampling has been noted.		
Change Filter			?	Oil and filter change at the time of sampling has been noted.		

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

Sample Rating Trend

VISCOSITY



Machine Id

11-1038 - JOHN DEERE EXCAVATOR

Component

Diesel Engine

PETRO CANADA DURON ADVANCED 10W30 (--- GAL)

DIAGNOSIS

Recommendation

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil.


Fluid Condition

The oil viscosity is higher than normal. The BN result indicates that there is suitable alkalinity remaining in the oil.

(00 / 041)						
30 (GAL)				Nov2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		SBP0004945		
Sample Date		Client Info		09 Nov 2023		
Machine Age	hrs	Client Info		3630		
Oil Age	hrs	Client Info		617		
Oil Changed		Client Info		Changed		
Sample Status				ATTENTION		
CONTAMINATIO	N	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0		
Water		WC Method	>0.2	NEG		
Glycol		WC Method		NEG		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	9		
Chromium	ppm	ASTM D5185m	>20	<1		
Nickel	ppm	ASTM D5185m	>4	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m	>3	0		
Aluminum	ppm	ASTM D5185m	>20	11		
Lead	ppm	ASTM D5185m	>40	<1		
Copper	ppm	ASTM D5185m	>330	0		
Tin	ppm	ASTM D5185m	>15	<1		
Vanadium	ppm	ASTM D5185m		<1		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	219		
Barium	ppm	ASTM D5185m	0	0		
Molybdenum	ppm	ASTM D5185m	60	241		
Manganese	ppm	ASTM D5185m	0	<1		
Magnesium	ppm	ASTM D5185m	1010	824		
Calcium	ppm	ASTM D5185m	1070	1406		
Phosphorus	ppm	ASTM D5185m	1150	924		
Zinc	ppm	ASTM D5185m	1270	1102		
Sulfur	ppm	ASTM D5185m	2060	2932		
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	8		
Sodium	ppm	ASTM D5185m		14		
Potassium	ppm	ASTM D5185m	>20	6		
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	0.5		
Nitration	Abs/cm	*ASTM D7624	>20	8.6		
Sulfation	Abs/.1mm	*ASTM D7415	>30	22.5		
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	16.8		
Base Number (BN)	mg KOH/g	ASTM D2896	10.0	9.4		
. ,						



OIL ANALYSIS REPORT







Laboratory Sample No. Lab Number Unique Number

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : SBP0004945 : 06010112

: 10749256

Received : 16 Nov 2023 Diagnosed

: 20 Nov 2023 Diagnostician : Don Baldridge

Test Package : FLEET (Additional Tests: KV40)

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

To discuss this sample report, contact Customer Service at 1-800-237-1369.

Constructors Inc. - 603659

1815 Y Street Lincoln, NE US 68508

Contact: Jack Linhart jackl@constructorslincoln.com

T: (402)434-2157 F: