

OIL ANALYSIS REPORT

Sample Rating Trend

VIS DEBRIS



HB-8 40W

Component
New (Unused) Oil
Fluid

{not provided} (--- GAL)

DIAGNOSIS

Recommendation

This is a baseline read-out on the submitted sample.


Contamination

Moderate concentration of visible dirt/debris present in the oil.

				Nov2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WCM249833		
Sample Date		Client Info		16 Nov 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m		<1		
Chromium	ppm	ASTM D5185m		0		
Nickel	ppm	ASTM D5185m		0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m		1		
Lead	ppm	ASTM D5185m		0		
Copper	ppm	ASTM D5185m		<1		
Tin	ppm	ASTM D5185m		0		
Vanadium	ppm	ASTM D5185m		<1		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		2		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		4		
Manganese	ppm	ASTM D5185m		0		
Magnesium	ppm	ASTM D5185m		23		
Calcium	ppm	ASTM D5185m		2015		
Phosphorus	ppm	ASTM D5185m		288		
Zinc	ppm	ASTM D5185m		365		
Sulfur	ppm	ASTM D5185m		2976		
CONTAMINANTS	}	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m		5		
Sodium	ppm	ASTM D5185m		<1		
Potassium	ppm	ASTM D5185m	>20	0		
Water	%	ASTM D6304		NEG		***
FLUID DEGRADA		and a the seal	limit/base		historya	hiotory?
I LOID DEGITION	ATION	method	iiiiii/base	current	history1	history2
Acid Number (AN)	MTION mg KOH/g	ASTM D8045	IIIIII/Dase	0.63		
			IIIIII/base			



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: WCM249833 : 06061595

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved : 16 Jan 2024

Diagnosed : 18 Jan 2024 Diagnostician : Jonathan Hester : MOB 2 (Additional Tests: FT-IR, ICP-NewOil, KF, KV100, PrtCount, TBN, VI)

METHANE POWER DURHAM - MAS ENERGY 2115 EAST CLUB BLVD

DURHAM, NC US 27704 Contact: DUSTIN

: 10832977 Test Package To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

T: (910)730-3493

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: DUSTIN? - METDUR

F: