

# **OIL ANALYSIS REPORT**

## Sample Rating Trend





TRANE 23572 C2 - VCU WOOD MEMORIAL (S/N U99K02834)
Component

**Refrigeration Compressor** 

**REFRIG COMP OIL ISO 68 (--- GAL)** 

## DIAGNOSIS

### Recommendation

Resample at the next service interval to monitor.

#### Wear

All component wear rates are normal.

### Contamination

There is no indication of any contamination in the component.

## **Fluid Condition**

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

3 00 ( GAL)			Jan 2023	Jan2024		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0632022	WC0632026	
Sample Date		Client Info		10 Jan 2024	17 Jan 2023	
Machine Age	hrs	Client Info		0	0	
Oil Age	hrs	Client Info		0	0	
Oil Changed		Client Info		N/A	N/A	
Sample Status				NORMAL	NORMAL	
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>8	0	0	
Chromium	ppm	ASTM D5185m	>2	0	0	
Nickel	ppm	ASTM D5185m		0	0	
Titanium	ppm	ASTM D5185m		0	0	
Silver	ppm	ASTM D5185m	>2	0	0	
Aluminum	ppm	ASTM D5185m	>3	0	0	
Lead	ppm	ASTM D5185m	>2	0	0	
Copper	ppm	ASTM D5185m	>8	<1	0	
Tin	ppm	ASTM D5185m	>4	0	0	
Vanadium	ppm	ASTM D5185m		<1	0	
Cadmium	ppm	ASTM D5185m		0	0	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	5	0	0	
Barium	ppm	ASTM D5185m	5	0	1	
Molybdenum	ppm	ASTM D5185m	5	0	0	
Manganese	ppm	ASTM D5185m		0	0	
Magnesium	ppm	ASTM D5185m	5	0	<1	
Calcium	ppm	ASTM D5185m	12	0	0	
Phosphorus	ppm	ASTM D5185m	12	0	7	
Zinc	ppm	ASTM D5185m	12	0	0	
Sulfur	ppm	ASTM D5185m	1000	314	0	
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	7	0	
Sodium	ppm	ASTM D5185m		0	0	
Potassium	ppm	ASTM D5185m	>20	0	<1	
Water	%	ASTM D6304	>0.01	0.003	0.002	
ppm Water	ppm	ASTM D6304	>100	35	24.5	
FLUID DEGRADA	NOITA	method	limit/base	current	history1	history2
	1/01::		0.10			


0.019

Acid Number (AN)

mg KOH/g ASTM D974 0.10



# **OIL ANALYSIS REPORT**







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** 

: WC0632022 : 06065710 : 10837092 Test Package : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 19 Jan 2024 Recieved

Diagnosed : 23 Jan 2024 : Angela Borella Diagnostician

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

**DAIKIN APPLIED-RICHMOND** 

3524 MAYLAND CT RICHMOND, VA US 23233

Contact: GANIS HEISLER ganis.heisler@daikin.com

T: (804)747-4822 F: (804)747-6686