

OIL ANALYSIS REPORT

Sample Rating Trend



Machine Id **M-224** Component **Gearbox** Fluid **MOBIL SHC 632 (--- GAL)**

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil.

Fluid Condition


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.


SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0887501	WC0747965	WC0453560
Sample Date		Client Info		01 Apr 2024	27 Sep 2023	29 Dec 2020
Machine Age	hrs	Client Info		90099	85613	61000
Oil Age	hrs	Client Info		27000	20000	8000
Oil Changed		Client Info		Not Changd	Not Changd	Not Changd
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINATION	٧	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	12	11	7
Chromium	ppm	ASTM D5185m	>10	0	0	0
Nickel	ppm	ASTM D5185m	>10	0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	<1
Aluminum	ppm	ASTM D5185m	>25	0	<1	0
Lead	ppm	ASTM D5185m	>50	0	0	0
Copper	ppm	ASTM D5185m	>200	0	0	0
Tin	ppm	ASTM D5185m	>10	0	0	0
Antimony	ppm	ASTM D5185m	>5			0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		3	2	6
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		0	<1	0
Magnesium	ppm	ASTM D5185m		0	0	0
Calcium	ppm	ASTM D5185m		0	0	<1
Phosphorus	ppm	ASTM D5185m		472	516	467
Zinc	ppm	ASTM D5185m		0	0	0
Sulfur	ppm	ASTM D5185m		148	57	83
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	24	24	21
Sodium	ppm	ASTM D5185m		0	0	0
Potassium	ppm	ASTM D5185m	>20	0	1	<1
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.60	0.56	0.646



OIL ANALYSIS REPORT

Acid Numbe	er		VISUAL
			White Metal
			Yellow Metal
			Precipitate
			Silt
			Debris
			Sand/Dirt
07/0	/23 -	Apr1/24 -	Appearance
המרקי	Sep 27/23	Apri	Odor
			Emulsified Water
/iscosity @ Abnormal	40°C		Free Water
			FLUID PROPER
Base			Visc @ 40°C
			SAMPLE IMAGI
Abnormal	1		
necz3/zu	1/23 -	Apr1/24 -	Color
772	Sep 27/23	Apri	
			Bottom
			Bottom GRAPHS
5 Base Numb			GRAPHS Iron (ppm)
			GRAPHS Iron (ppm)
Base Numb	ber		GRAPHS Iron (ppm)
Base Numb	ber		GRAPHS Iron (ppm)
Base Numb			GRAPHS Iron (ppm)
Base Numb	ber		GRAPHS Iron (ppm)
Base Numb	ber	A1 0.4	GRAPHS Iron (ppm) ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰
Base Numb	ber	A1 0.4	GRAPHS Iron (ppm) ⁶⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰⁰ ⁴⁰
Base Numb	ber	A1 0.4	GRAPHS Iron (ppm) ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰
Base Numb	ber	A1 0.4	GRAPHS Iron (ppm) 400 400 400 400 500 400 600 600 600 600 600 600 6
Base Numb	ber	A1 0.4	GRAPHS Iron (ppm) ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰
Base Numb	ber	A1 0.4	GRAPHS Iron (ppm) ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰⁰ ⁶⁰
Base Numb	ber	And And	GRAPHS Iron (ppm) ⁶⁰⁰ ^{8evere} ²⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁶⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere}
	ber	And And	GRAPHS Iron (ppm) ⁶⁰⁰ ^{8evere} ²⁰⁰ ^{8evere} ²⁰⁰ ^{8evere} ²⁰⁰ ^{8evere} ²⁰⁰ ^{8evere} ²⁰⁰ ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere}
Base Numb	ber	And And	GRAPHS Iron (ppm) ⁶⁰⁰ ^{8evere} ²⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁶⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ⁴⁰⁰ ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere} ^{8evere}





() 00 350

ઝું 300

Laboratory

Sample No.

250

Der 29

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: KBBAKR [WUSCAR] 06141518 (Generated: 04/11/2024 13:52:09) Rev: 1

Certificate 12367

Contact/Location: ERIC FOX - KBBAKR

ericf@kbbioenergy.com;jwatson@wearcheckusa.com

Page 2 of 2

Contact: ERIC FOX

T: (330)864-2621

F: (330)864-7023