


OIL ANALYSIS REPORT

Sample Rating Trend

RING CONTAINER EXTRUDER O - MAIN PLANT

Hydraulic System

SHELL TELLUS 46 (--- GAL)





Recommendation

Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

Wear

All component wear rates are normal.

Contamination

The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
	MATION		IIIIIIIIIIII	WC0892740	•	WC0855531
Sample Number Sample Date		Client Info		02 Apr 2024	WC0891190 25 Jan 2024	18 Oct 2023
Machine Age	hrs	Client Info		02 Apr 2024 0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed	1110	Client Info		Not Changd	Not Changd	Not Changd
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINATION	٧	method	limit/base	current	history1	history2
Water		WC Method	>0.05	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	11	12	14
Chromium	ppm	ASTM D5185m	>20	<1	<1	<1
Nickel	ppm	ASTM D5185m	>20	0	0	0
Titanium	ppm	ASTM D5185m		0	<1	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>20	0	0	<1
Lead	ppm	ASTM D5185m	>20	0	0	0
Copper	ppm	ASTM D5185m	>20	4	5	4
Tin	ppm	ASTM D5185m	>20	<1	0	<1
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		0	0	<1
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0.0	0	0	0
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	0	93	93	90
Manganese	ppm	ASTM D5185m		<1	0	0
Magnesium	ppm	ASTM D5185m	11	0	0	<1
Calcium	ppm	ASTM D5185m	35	23	10	20
Phosphorus	ppm	ASTM D5185m	266	331	342	353
Zinc	ppm	ASTM D5185m	276	184	183	251
Sulfur	ppm	ASTM D5185m	1847	2192	1853	1930
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	6	6	7
Sodium	ppm	ASTM D5185m		2	1	1
Potassium	ppm	ASTM D5185m	>20	0	0	1
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	1236	1944	651
Particles >6µm		ASTM D7647	>1300	274	322	137
Particles >14μm		ASTM D7647	>160	17	37	11
Particles >21µm		ASTM D7647	>40	3	13	4
Particles >38μm		ASTM D7647	>10	0	0	0
Particles >71µm		ASTM D7647	>3	0	0	0
Oil Cleanliness		ISO 4406 (c)	>19/17/14	17/15/11	18/16/12	17/14/11
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
A : INI (ANI)	1/011/	4 OT1 4 D 00 4 F			0 = 1 =	


Acid Number (AN)


mg KOH/g ASTM D8045 0.36


0.57




OIL ANALYSIS REPORT









VISUAL		method				history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.05	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
		l	Para Maria and		for the control	la la la va o


FLUID PROPER	THES	method	ilmit/base		nistory i	nistory2
Visc @ 40°C	cSt	ASTM D445	46.99	44.2	48.0	44.2

SAMPLE IMAGES	method				history2
---------------	--------	--	--	--	----------

Color











Certificate 12367

Laboratory Sample No.

: WC0892740 Lab Number : 06143006 Unique Number : 10967814

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 09 Apr 2024 **Tested** : 10 Apr 2024

Diagnosed

: 10 Apr 2024 - Wes Davis

Contact: Bill Trimmer btrimmer@motortechnologyinc.com T: (717)266-4045

MOTOR TECHNOLOGY INC

515 WILLOW SPRINGS LN

Test Package : IND 2 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Submitted By: Bill Trimmer

YORK, PA

US 17406