







**FUEL REPORT**

**GRAPHS**



**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513  
**Sample No.** : VCP331655 **Received** : 16 Apr 2024  
**Lab Number** : **06150855** **Tested** : 19 Apr 2024  
**Unique Number** : 10980933 **Diagnosed** : 19 Apr 2024 - Jonathan Hester  
**Test Package** : MOB 1 ( Additional Tests: KF )

**MCCLUNG-LOGAN EQUIPMENT CO - RICHMOND**  
 1345 MOUNTAIN ROAD  
 GLEN ALLEN, VA  
 US 23060  
 Contact: KYLE RATLIFFE  
 KRATLIFFE@MCCLUNG-LOGAN.COM

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (804)266-1611