


OIL ANALYSIS REPORT

Sample Rating Trend



Machine Id

FS CURTIS HE13E23061 - MILL 3

Compressor

PG 32 (--- GAL)

DIAGNOSIS

Recommendation

We suspect abnormal contamination may be due to sampling method. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

Moderate concentration of visible metal present. All component wear rates are normal.

Contamination

There is no indication of any contamination in the

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORM	ATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0897658		
Sample Date		Client Info		23 Apr 2024		
Machine Age	hrs	Client Info		4128		
Oil Age	hrs	Client Info		4128		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	<1		
Chromium	ppm	ASTM D5185m	>10	<1		
Nickel	ppm	ASTM D5185m		1		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		<1		
Aluminum	ppm	ASTM D5185m	>25	2		
Lead	ppm	ASTM D5185m	>25	3		
Copper	ppm	ASTM D5185m	>50	2		
Tin	ppm	ASTM D5185m	>15	1		
Vanadium	ppm	ASTM D5185m		<1		
Cadmium	ppm	ASTM D5185m		<1		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		189		
Molybdenum	ppm	ASTM D5185m		1		
Manganese	ppm	ASTM D5185m		1		
Magnesium	ppm	ASTM D5185m		11		
Calcium	ppm	ASTM D5185m		7		
Phosphorus	ppm	ASTM D5185m		169		
Zinc	ppm	ASTM D5185m		<1		
Sulfur	ppm	ASTM D5185m		828		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	21		
Sodium	ppm	ASTM D5185m		53		
Potassium	ppm	ASTM D5185m	>20	6		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2


0.33


Acid Number (AN)


mg KOH/g ASTM D8045





OIL ANALYSIS REPORT















Certificate 12367

Laboratory Sample No.

Lab Number : 06159831

: WC0897658 Unique Number : 10995254 Test Package : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 24 Apr 2024 **Tested** : 29 Apr 2024

Diagnosed

: 30 Apr 2024 - Jonathan Hester

Contact: Robert York robert.york@fs-compression.com

FS-COMPRESSION CO, LLC

203 AERO COURT

F: (336)605-9844

GREENSBORO, NC

To discuss this sample report, contact Customer Service at 1-800-237-1369. st - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: AIRGREWC [WUSCAR] 06159831 (Generated: 04/30/2024 12:07:15) Rev: 1

Contact/Location: Robert York - AIRGREWC

US 27409

T: