

FUEL REPORT

Bottom

Sample Rating Trend

NORMAL

Machine Id

Dutchess County Government Building 2097886

Component Diesel Fuel

Fluid No.2 DIESEL FUEL (ULTRALOW SULPHUR) (--- GAL)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time.

Corrosion

All metal levels are normal indicating no corrosion in the system.


Contaminants

There is no indication of any contamination in the fuel.

Fuel Condition

The condition of the fuel is acceptable for the time in service.


SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0921720	WC0799884	WC0651437
Sample Date		Client Info		20 May 2024	02 May 2023	22 Apr 2022
Machine Age	hrs	Client Info		0	0	0
Sample Status				NORMAL	NORMAL	NORMAL
SULFUR CONTEN	ΝT	method	limit/base	current	history1	history2
Sulfur	ppm	ASTM D5185m	10	1	0	0
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	<1.0	<1	0	<1
Sodium	ppm	ASTM D5185m	<0.1	<1	0	0
Potassium	ppm	ASTM D5185m	<0.1	0	<1	0
HEAVY METALS		method	limit/base	current	history1	history2
Aluminum	ppm	ASTM D5185m	<0.1	0	0	0
Nickel	ppm	ASTM D5185m	<0.1	0	0	0
Lead	ppm	ASTM D5185m	<0.1	0	0	0
Vanadium	ppm	ASTM D5185m	<0.1	<1	0	0
Iron	ppm	ASTM D5185m	<0.1	0	0	<1
Calcium	ppm	ASTM D5185m	<0.1	0	0	0
Magnesium	ppm	ASTM D5185m	<0.1	<1	3	0
Phosphorus	ppm	ASTM D5185m	<0.1	0	8	7
Zinc	ppm	ASTM D5185m	<0.1	0	0	0
SAMPLE IMAGES	;	method	limit/base	current	history1	history2
Color				a. •		





FUEL REPORT

GRAPHS



Contact/Location: JOE SAYEGH - GENNEW