

OIL ANALYSIS REPORT

Sample Rating Trend



Machine Id

NISSEI IMM309

Hydraulic System

MOBIL DTE 10 EXCEL 46 (85 GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample.

Wear

All component wear rates are normal.

Contamination

There is a moderate amount of visible silt present in the sample.


Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0887714		
Sample Date		Client Info		01 Mar 2024		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
CONTAMINATION	V	method	limit/base	current	history1	history2
Water		WC Method	>0.05	NEG		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	4		
Chromium	ppm	ASTM D5185m	>20	<1		
Nickel	ppm	ASTM D5185m	>20	0		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>20	2		
Lead	ppm	ASTM D5185m	>20	<1		
Copper	ppm	ASTM D5185m	>20	7		
Tin	ppm	ASTM D5185m	>20	<1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		2		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m		<1		
Calcium	ppm	ASTM D5185m		97		
Phosphorus	ppm	ASTM D5185m		438		
Zinc	ppm	ASTM D5185m		29		
Sulfur	ppm	ASTM D5185m		1999		
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	<1		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	1		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.136		




OIL ANALYSIS REPORT









Non-ferrous Metals











Laboratory Sample No.

Lab Number : 06210720

: WC0887714 Unique Number : 11083584

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 14 Jun 2024 : 19 Jun 2024 Tested

Diagnosed : 19 Jun 2024 - Angela Borella

Sumitomo Electric Wiring Systems 2687 Old Gallatin Road, Plant 5

Scottsville, KY US 42164

Contact: BILLY CARDER bcarder@sewsus.com

T: (270)237-5419 F: (270)237-9476

Test Package : IND 2 Certificate 12367

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) Report Id: SUMSCO [WUSCAR] 06210720 (Generated: 06/22/2024 21:45:53) Rev: 1

Contact/Location: BILLY CARDER - SUMSCO