

## **OIL ANALYSIS REPORT**



Machine Id

FASSI 2301-5231

Hydraulic System Fluid AW HYDRAULIC OIL ISO 46 (--- LTR)

### DIAGNOSIS

#### Recommendation

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) AW HYDRAULIC OIL ISO 46. Please confirm.

#### Wear

All component wear rates are normal.

#### Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.

#### Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.


SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0778102		
Sample Date		Client Info		31 Mar 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		Not Changd		
Sample Status				SEVERE		
CONTAMINATIO	N	method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	12		
Chromium	ppm	ASTM D5185m	>10	2		
Nickel	ppm	ASTM D5185m	>10	<1		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>10	2		
Lead	ppm	ASTM D5185m	>10	<1		
Copper	ppm	ASTM D5185m	>75	<1		
Tin	ppm	ASTM D5185m	>10	<1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		<1		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	5	0		
Barium	ppm	ASTM D5185m	5	0		
Molybdenum	ppm	ASTM D5185m	5	<1		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m	25	2		
Calcium	ppm	ASTM D5185m	200	37		
Phosphorus	ppm	ASTM D5185m	300	284		
Zinc	ppm	ASTM D5185m	370	366		
Sulfur	ppm	ASTM D5185m	2500	2116		
CONTAMINANTS	\$	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	4		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	<1		
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	<b>1</b> 34782		
Particles >6µm		ASTM D7647	>1300	<b>4</b> 38968		
Particles >14µm		ASTM D7647	>160	<u> </u>		
Particles >21µm		ASTM D7647	>40	16		
Particles >38µm		ASTM D7647	>10	0		
Particles >71µm		ASTM D7647	>3	0		
Oil Cleanliness		ISO 4406 (c)	>19/17/14	<b>4</b> 24/22/15		
FLUID DEGRADA		method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.57	0.25		
			 -			


Report Id: CARHIGMO [WUSCAR] 06211555 (Generated: 06/21/2024 23:54:50) Rev: 1

Contact/Location: BRETT HIGGINS - CARHIGMO



# **OIL ANALYSIS REPORT**





Received

Diagnosed

Tested

Test Package : MOB 2 (Additional Tests: KV100, VI)

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: 17 Jun 2024

: 18 Jun 2024

: 18 Jun 2024 - Wes Davis



2367 CASSENS DR FENTON, MO US 63026 Contact: BRETT HIGGINS brett.higgins@hiab.com T: (636)575-5136 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (636)677-5800

Report Id: CARHIGMO [WUSCAR] 06211555 (Generated: 06/21/2024 23:54:50) Rev: 1

Certificate 12367

Contact/Location: BRETT HIGGINS - CARHIGMO