


OIL ANALYSIS REPORT

Sample Rating Trend





TBN Machine Id TBN-QC10

Component **Oil** Fluid


{not provided} (--- GAL)

DIAGNOSIS


| SAMPLE INFORM | MATION | method | limit/base | current | history1 | history2 |
|---------------|--------|-------------|------------|-------------|-------------|-------------|
| Sample Date | | Client Info | | 05 May 2023 | 05 May 2023 | 04 May 2023 |
| Machine Age | HR | Client Info | | 0 | 0 | 0 |
| Oil Age | HR | Client Info | | 0 | 0 | 0 |
| Oil Changed | | Client Info | | N/A | N/A | N/A |
| Sample Status | | | | NORMAL | NORMAL | NORMAL |
| SAMPLE IMAGES | 5 | method | limit/base | current | history1 | history2 |
| Color | | | | no image | no image | no image |
| Bottom | | | | no image | no image | no image |



OIL ANALYSIS REPORT



Non-ferrous Metals





Certificate L2367

Laboratory Sample No. Lab Number

: Q0004GGM Unique Number : 15893462 Test Package : TEST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 06 Jun 2023 Received

Diagnosed : 02 Oct 2023 Diagnostician : System

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050