


TBN-QC10

{not provided} (--- GAL)

OIL ANALYSIS REPORT

Sample Rating Trend





NORMAL

SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Date		Client Info		26 Apr 2023	26 Apr 2023	26 Apr 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				NORMAL	NORMAL	NORMAL
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image


Area TBN

Component **Oil** Fluid

Report Id: WEACARQA [WUSCAR] Q0004GH0 (Generated: 10/03/2023 15:33:50) Rev: 1



OIL ANALYSIS REPORT



: WearCheck USA - 501 Madison Ave., Cary, NC 27513 WEARCHECK LUBRICATION SERVICES QA ACCOUNT Laboratory : 06 Jun 2023 Sample No. Received 501 Madison Ave Lab Number : Q0004GH0 Diagnosed : 02 Oct 2023 Cary, NC Unique Number : 15893476 Diagnostician : System US 27513 Test Package : TEST Contact: WCLS CARY NC Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 F: (919)379-4050

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)