


## **OIL ANALYSIS REPORT**

Sample Rating Trend





PrtCount
Machine Id
APC-2-PCS

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS


SAMPLE INFORMATION		method	limit/base	current	history 1	history 2
Sample Date		Client Info		03 Jul 2023	30 Jun 2023	30 Jun 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						

SAMPLE IMAGES	method	limit/base	current	history 1	history 2	
Color			no image	no image	no image	
Bottom			no image	no image	no image	




## **OIL ANALYSIS REPORT**

## **GRAPHS**



## Non-ferrous Metals





Certificate L2367

Laboratory Sample No. Lab Number

Unique Number : 16000386 Test Package : TEST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : Q0004H9F

Received Diagnosed

: 03 Jul 2023 : 03 Jul 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

T: (919)379-4102

F: (919)379-4050

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)