

## **OIL ANALYSIS REPORT**

#### Sample Rating Trend



# Area TBN TBN-QC6 Component **Oil** Fluid {not provided} (--- GAL)

#### DIAGNOSIS

																10							
	1		Т			Г	Г	E I	г.			Ц,	Т.	г I		U				1	Т.	г	
		22	4	2.	2	 ÷		-		÷.		 	 		-	÷.,	2.				 4	÷.	2
1.1																							
t en er																							
6 I I I																							
1.1.1																							
1																							
1.1.1																							
1.1.1																							




#### 2023 Jun2023 Jun2023 Jun202

SAMPLE INFORM	IATION	method	limit/base	current	history 1	history 2
Sample Date		Client Info		05 Jul 2023	03 Jul 2023	03 Jul 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
SAMPLE IMAGES	;	method	limit/base	current	history 1	history 2
Color				no image	no image	no image
Bottom				no image	no image	no image



### **OIL ANALYSIS REPORT**



: WearCheck USA - 501 Madison Ave., Cary, NC 27513 WEARCHECK LUBRICATION SERVICES QA ACCOUNT Laboratory Sample No. Received : 06 Jul 2023 501 Madison Ave Lab Number : Q0004HAW Diagnosed : 06 Jul 2023 Cary, NC Unique Number : 16000827 Diagnostician : Wes Davis US 27513 Test Package : TEST Contact: WCLS CARY NC Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)