


# **OIL ANALYSIS REPORT**

## Sample Rating Trend





SAMPLE INFORMATION		method	limit/base	current	history 1	history 2
Sample Date		Client Info		06 Jul 2023	05 Jul 2023	05 Jul 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
SAMPLE IMAGES		method	limit/base	current	history 1	history 2
Color				no image	no image	no image
Bottom				no image	no image	no image


Area KF-2-QC Component Oil Fluid {not provided} (--- GAL)

### DIAGNOSIS

Report Id: WEACARQA [WUSCAR] Q0004HBB (Generated: 07/06/2023 08:54:25) Rev: 1



## **OIL ANALYSIS REPORT**



: WearCheck USA - 501 Madison Ave., Cary, NC 27513 WEARCHECK LUBRICATION SERVICES QA ACCOUNT Laboratory Sample No. Received : 06 Jul 2023 501 Madison Ave Lab Number : Q0004HBB Diagnosed : 06 Jul 2023 Cary, NC Unique Number : 16000848 Diagnostician : Wes Davis US 27513 Test Package : TEST Contact: WCLS CARY NC Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: WCLS CARY NC ? - WEACARQA