

# **OIL ANALYSIS REPORT**

### Sample Rating Trend



## TAN Man Machine Id TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

### DIAGNOSIS


SAMPLE INFORMATION		method	limit/base	current	history 1	history 2
Sample Date		Client Info		12 Jul 2023	12 Jul 2023	12 Jul 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
SAMPLE IMAGES		method	limit/base	current	history 1	history 2
Color				no image	no image	no image
Bottom				no image	no image	no image

-3022 lus 2022 lus 2022 lus 2022 lus 2022 lus 2023 lus 20




## **OIL ANALYSIS REPORT**


#### **GRAPHS**







#### Viscosity @ 40°C





Certificate L2367

Laboratory Sample No. Lab Number

: Q0004HF2 Unique Number : 16001412 Test Package : TEST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 12 Jul 2023

Diagnosed : 12 Jul 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

T: (919)379-4102

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (919)379-4050