

## **OIL ANALYSIS REPORT**

## Sample Rating Trend



TAN Man
Machine Id
TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

#### DIAGNOSIS


SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Date		Client Info		26 Jul 2023	25 Jul 2023	24 Jul 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image

2022 Lu2023 Lu2023 Lu2023 Lu2023 Lu2023 Lu2024




### **OIL ANALYSIS REPORT**

#### **GRAPHS**







# Viscosity @ 40°C 0.8 0.4 cSt (40°C) -0.2 -0.4 -0.8



Certificate L2367

Laboratory Sample No. Lab Number

Test Package : TEST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 26 Jul 2023 : 26 Jul 2023

: Q0004HM0 Diagnosed Unique Number : 16004444 Diagnostician : Wes Davis

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

Contact: WCLS CARY NC

T: (919)379-4102 F: (919)379-4050