

## **OIL ANALYSIS REPORT**

### Sample Rating Trend



# TAN Auto Machine Id AutoTAN-1-QC

Component **Oil** Fluid

{not provided} (--- GAL)

#### DIAGNOSIS

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Date		Client Info		25 Jul 2023	25 Jul 2023	25 Jul 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
SAMPLE IMAGES	3	method	limit/base	current	history1	history2


-3022 Lu7022 Lu7022 Lu7022 Lu7022 Lu7023 Lu7023 Lu7023

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	no image
Bottom			no image	no image	no image




## **OIL ANALYSIS REPORT**


#### **GRAPHS**







# Viscosity @ 40°C





Certificate L2367

Laboratory Sample No. Test Package : TEST

Lab Number

: Q0004HMY Unique Number : 16004575

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 27 Jul 2023 : 27 Jul 2023

Diagnosed Diagnostician : Wes Davis WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: (919)379-4102 F: (919)379-4050