

# **OIL ANALYSIS REPORT**

#### Sample Rating Trend





### 

| SAMPLE INFORMATION |    | method      | limit/base | current     | history1    | history2    |
|--------------------|----|-------------|------------|-------------|-------------|-------------|
| Sample Date        |    | Client Info |            | 02 Aug 2023 | 02 Aug 2023 | 01 Aug 2023 |
| Machine Age        | HR | Client Info |            | 0           | 0           | 0           |
| Oil Age            | HR | Client Info |            | 0           | 0           | 0           |
| Oil Changed        |    | Client Info |            | N/A         | N/A         | N/A         |
| Sample Status      |    |             |            |             |             |             |
| SAMPLE IMAGES      |    | method      | limit/base | current     | history1    | history2    |
| Color              |    |             |            | no image    | no image    | no image    |
| Bottom             |    |             |            | no image    | no image    | no image    |


#### Area TBN Machine Id TBN-QC6 Component

Component Oil Fluid {not provided} (--- GAL)

## DIAGNOSIS



## **OIL ANALYSIS REPORT**



: WearCheck USA - 501 Madison Ave., Cary, NC 27513 WEARCHECK LUBRICATION SERVICES QA ACCOUNT Laboratory Sample No. Received : 03 Aug 2023 501 Madison Ave : Q0004HPV Lab Number Diagnosed : 03 Aug 2023 Cary, NC Unique Number : 16007152 Diagnostician : Wes Davis US 27513 Test Package : TEST Contact: WCLS CARY NC Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050

Report Id: WEACARQA [WUSCAR] Q0004HPV (Generated: 08/04/2023 01:10:09) Rev: 1

Contact/Location: WCLS CARY NC ? - WEACARQA