


# **OIL ANALYSIS REPORT**

### Sample Rating Trend





TAN Auto AutoTAN-1-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS


SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		04 Aug 2023	04 Aug 2023	03 Aug 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	no image
Bottom			no image	no image	no image




## **OIL ANALYSIS REPORT**


#### **GRAPHS**







#### Viscosity @ 40°C





Certificate L2367

Laboratory Sample No. Lab Number Test Package : TEST

Unique Number : 16007666

: Q0004HRA

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 07 Aug 2023

Diagnosed : 07 Aug 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

T: (919)379-4102

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (919)379-4050