

# **OIL ANALYSIS REPORT**

#### Sample Rating Trend





## n2023 Jun2023 Jun2023 Jul2023 Jul2023 Jul2023 Jul2023 Jul2023

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		07 Aug 2023	07 Aug 2023	07 Aug 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
SAMPLE IMAGES	\$	method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image


#### Area **FT-IR** Machine Id **FTIR-1-QC** Component **Oil** Fluid

{not provided} (--- GAL)

### DIAGNOSIS



## **OIL ANALYSIS REPORT**



: WearCheck USA - 501 Madison Ave., Cary, NC 27513 WEARCHECK LUBRICATION SERVICES QA ACCOUNT Laboratory Sample No. Received : 07 Aug 2023 501 Madison Ave Lab Number : Q0004HST Diagnosed : 07 Aug 2023 Cary, NC Unique Number : 16007721 Diagnostician : Wes Davis US 27513 Test Package : TEST Contact: WCLS CARY NC Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: WCLS CARY NC ? - WEACARQA