


TAN Auto

# **OIL ANALYSIS REPORT**

## Sample Rating Trend





AutoTAN-1-QC
Component
Oil
Fluid

{not provided} (--- GAL)

## DIAGNOSIS


SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		07 Aug 2023	07 Aug 2023	04 Aug 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	no image
Bottom			no image	no image	no image





## **OIL ANALYSIS REPORT**

### **GRAPHS**



#### Non-ferrous Metals







Certificate L2367

Laboratory Sample No. Lab Number Test Package : TEST

Unique Number : 16007841

: Q0004HTB

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 08 Aug 2023

Diagnosed : 08 Aug 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050