


## **OIL ANALYSIS REPORT**

Sample Rating Trend





Machine Id
KF-1-QC
Component
Oil
Fluid
{not provided} (--- GAL)

DIAGNOSIS


| SAMPLE INFORMATION |    | method      | limit/base | current     | history1    | history2    |
|--------------------|----|-------------|------------|-------------|-------------|-------------|
| Sample Date        |    | Client Info |            | 09 Aug 2023 | 08 Aug 2023 | 07 Aug 2023 |
| Machine Age        | HR | Client Info |            | 0           | 0           | 0           |
| Oil Age            | HR | Client Info |            | 0           | 0           | 0           |
| Oil Changed        |    | Client Info |            | N/A         | N/A         | N/A         |
| Sample Status      |    |             |            |             |             |             |

| SAMPLE IMAGES | method | limit/base | current  | history1 | history2 |
|---------------|--------|------------|----------|----------|----------|
| Color         |        |            | no image | no image | no image |
| Bottom        |        |            | no image | no image | no image |




## **OIL ANALYSIS REPORT**

## **GRAPHS**



## Non-ferrous Metals





Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 16008265

: Q0004HUV

Test Package : TEST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 10 Aug 2023

Diagnosed : 10 Aug 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave

Cary, NC US 27513

T: (919)379-4102

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (919)379-4050