

OIL ANALYSIS REPORT

Sample Rating Trend



Area Machine Id ARCOS-1-AM/900 Component Oil Fluid {not provided} (--- GAL)

DIAGNOSIS

[concerns]		
111111		
1.1.1.1.1.1		
1.1.1.1.1.1		
100000		
1.1.1.1		
1.1.1.1.1.1		
1.1.1.1.1.1		




2023 Aug2023 Aug2023 Aug2023 Aug2023 Aug2023 Aug2023 Aug2023 Aug2023

SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Date		Client Info		14 Aug 2023	14 Aug 2023	14 Aug 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				NORMAL		NORMAL
SAMPLE IMAGES	\$	method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image



OIL ANALYSIS REPORT



: WearCheck USA - 501 Madison Ave., Cary, NC 27513 WEARCHECK LUBRICATION SERVICES QA ACCOUNT Laboratory Sample No. Received : 14 Aug 2023 501 Madison Ave Lab Number : Q0004HZ8 Diagnosed : 14 Aug 2023 Cary, NC Unique Number : 16009227 Diagnostician : Wes Davis US 27513 Test Package : TEST Contact: WCLS CARY NC Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 F: (919)379-4050

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Page 2 of 2